



# Turners Certified Imports 50 Point Check

Report ID: 19,161,193

Version: 1

Created: 12 Apr 2019

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has undergone a thorough compliance check by an NZTA accredited inspection agency and been test driven up to 50km/h from cold.

Make: Mazda Body Style: Hatchback  
Model: Axela Odometer: 87,192 Kms  
Year: 2012 VIN: 7AT0C13JX19106182

Under Carriage & Under Bonnet Inspection Comments

Tyre repair kit

General Comments

Seats: driver seat worn

Carpets: Average

Panels: Average

Dashboard: Average

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable

Replaced At (odometer reading):

Road Conditions During Test Drive: Dry

**Electrical**

Battery	<input checked="" type="checkbox"/>
Head lights	<input checked="" type="checkbox"/>
Tail lights	<input checked="" type="checkbox"/>
Indicators	<input checked="" type="checkbox"/>
Dashboard warning lights	<input checked="" type="checkbox"/>
Wipers (front & rear)	<input checked="" type="checkbox"/>
Window winder FL	<input checked="" type="checkbox"/>
Window winder FR	<input checked="" type="checkbox"/>
Window winder RL	<input checked="" type="checkbox"/>
Window winder RR	<input checked="" type="checkbox"/>
Rear view mirrors	<input checked="" type="checkbox"/>
Radio (basic test only)	<input checked="" type="checkbox"/>
CD (basic test only)	<input checked="" type="checkbox"/>
Reversing camera	<input type="checkbox"/>

**Transmission & Drive**

Operation	<input checked="" type="checkbox"/>
Noise	<input checked="" type="checkbox"/>
Clutch	<input type="checkbox"/>
CV joints	<input checked="" type="checkbox"/>
Wheel bearings	<input checked="" type="checkbox"/>
Wheel balance	<input checked="" type="checkbox"/>

**Brakes**

Performance	<input checked="" type="checkbox"/>
Hand Brake	<input checked="" type="checkbox"/>

**Keys & Locking**

Central locking	<input checked="" type="checkbox"/>
Remote locking	<input checked="" type="checkbox"/>
Number of keys	2

**Engine**

Oil level	<input checked="" type="checkbox"/>
Smoke & fumes	<input checked="" type="checkbox"/>
Performance	<input checked="" type="checkbox"/>
Noise	<input checked="" type="checkbox"/>

**Cooling System**

Coolant condition	<input checked="" type="checkbox"/>
Performance	<input checked="" type="checkbox"/>
Radiator / Hoses (visual)	<input checked="" type="checkbox"/>

**Suspension**

Suspension performance	<input checked="" type="checkbox"/>
Steering performance	<input checked="" type="checkbox"/>
Shock absorbers	<input checked="" type="checkbox"/>

**Tyres** (lowest observed tread depth)

Left front	5 mm
Right front	6 mm
Left rear	5 mm
Right rear	5 mm
Spare	N/A
Tools	<input checked="" type="checkbox"/>

**Interior**

AC Operation	<input checked="" type="checkbox"/>
Heater fan	<input checked="" type="checkbox"/>
Seatbelts	<input checked="" type="checkbox"/>
Horn	<input checked="" type="checkbox"/>

**Turners Certified Key**

✓ = Pass      ✗ = Fail  
• = Not applicable for this vehicle

Inspected by: John Lindsay

Date: 12 Apr 2019

I have read and understood this condition guide.

Name: .....

Signature: .....