

Basic Vehicle Condition Guide

Report ID: 19,162,372


Version: 2

Created: 10 Jun 2019

Make: Model: Hyundai Coupe **Body Style:** Sedan Year: 2002 Registration: FCR806 Reg Expiry: 05 May 2019 WoF Expiry: **Odometer: Good No:** 30 May 2020 139,222 Kms 19162372 VIN: KMHHN61FR3U05592 **Next Service:** 146000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



body inspection comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	driver seat worn			
Carpets	Average			
Panels	Average			
Dashboard	Average			

General Comments

Knock in rear suspension

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes

Kms: 104,592

Inspected by:	John Lindsay	Date:	10 Jun 2019
---------------	--------------	-------	-------------

Create			019
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	<i>v</i>		
Performance	~		
Noise	~		
Cooling System			1
Coolant condition	~		
Performance	\(\sigma \)		
Radiator / Hoses (visual)	~		
Transmission	!		1
Operation	~		
Noise 🗸			
Clutch			·
CV joints	~		
Wheel bearings	~		
Brakes			<u> </u>
Performance	V		
Hand Brake	<i>'</i>		
Tyres (lowest observed tread	denth	of tyre	25)
Left front			mm
Right front	6		mm
Left rear	6		mm
Right rear	3		mm
Spare		4	111111
Suspension		Yes	
Suspension performance			
Steering performance	_		
Shock absorbers			
	<i>'</i>		
Air Conditioning / Heater	I		1
Operation		•	
Electrical / Accessories			_
Head lights	V		
Tail lights			
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	<i>'</i>		
Window winder FR	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>		
Window winder RL	v		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~
	19		

I have read and understood this condition guide.

Name:

Signature: