

Report ID: 19,162,449 Version: 2 26 Apr 2019 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Sedan		Pass	Fail	N/A
Year:	1998		WY1901	Reg Expiry:	30 Jul 2019	Engine			
WoF Expiry:		Odometer:	108,009 Kms	Good No:	19162449	Oil level	~		
VIN:	7A453AEB208000305	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II	<b>D</b>		Noise		~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	S D PT W	-0	SD SDPT		S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent S SC W D B S W						Operation	~		
R = rust PT = paint def				$\prod$	JHIH	Noise	~		
C = crack					D R SC	Clutch	•		~
P = pin dent						CV joints	~		
* = decals	SDRSC 91			- AL	EL SDR	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SD W SDR SD W SDR						Performance	~		1
		Note <sup>,</sup> som	e defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		-
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed treat	•	oftyre	
Chips windscreen Bonnet alignment						Left front 2 mm			
bonneeding						Right front			mm
						Left rear			
						Right rear	3 mm		
Conditions During Body Inspection: Dry							3 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
<u></u>						Suspension performance	~		
						Steering performance			<u> </u>
						Shock absorbers	レ レ		<u> </u>
							V		
						Air Conditioning / Heater			1
Interior Comments						Operation   Electrical / Accessories			
driver seat worn, burn holes front passenger seat						Head lights			T
Seats							~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	ord screw hole	es in centre conso	ble			Wipers (front & rear)	~		
						Window winder FL	~		
General (	omments					Window winder FR	~		
General Comments Engine belts noisy						Window winder RL	~		
	,					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		1
Road Conditions During Test Drive: Dry						Central locking	~		<u> </u>
Engine Timing Mechanism: Cambelt						Remote locking	~		<b> </b>
Evidence of Cam Belt Replacement: Yes Kms: 87,000						Sat. Nav. (basic test only)			~
Lvidence		ciliciit. Y	53	ιτιτο. δ/	,000	Reversing camera			~
Inspected by: John Lindsay Date: 26 Apr 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....