

Report ID: 19,162,859 Version: 2 15 Apr 2019 Created:

Make:	KIA	Model:	RIO	Body Style:	Hatchback	1		Pass	Fail	N/A
Year:	2006	Registration:DQJ979Reg Expiry:29 Jul 2019			Engine	Engine				
WoF Expiry:	15 Apr 2020	Odometer:	128,900 Kms	900 Kms Good No: 19162859			el	~		
VIN:	KNADE243376186523	Next Service:	128,734	Service Histor	y: No	Smoke	e & fumes	~		
						Perfor	mance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise		~		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling	Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition			
						Perfor	mance	~		
Key:	L	-0	W PT SC V	s M S	sc	Radiat	or / Hoses (visual)	~		
S = scratch						Transm	ission			1
						Opera	Operation			
R = rust PT = paint defect						Noise		~		
C = crack					PT	Clutch				~
P = pin dent	-110				세비	CV joir	nts	~		-
* = decals						<u> </u>	bearings	~		
SC = stone chips						Brakes				
W = significant scuffs S P W S PT P W S PT P W S PT P W						Perfor	~	~		
D. L.L.		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand	Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				es)
Stone chips in the windscreen,						ļ	Left front 6 mr			
						Right f		6		mm
							Left rear		2	mm
Conditions During Body Inspection: Dry							Right rear		2 mm	
Conditions During Body Inspection: Dry						Spare				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Coolant level low,						· · ·	nsion performance	~		
							ng performance	~		
							absorbers	~		
						Air Conditioning / Heater				
						Operation V				
Interior Comments						Electrical / Accessories				
Seats Good					Head I		~			
	Card					Tail lig	5	~		
Carpets	Good					Indicat		~		
Panels	wear and t	ear					oard warning lights	~		
							s (front & rear)	~		
Dashboa	rd Good						w winder FL	~		
]	w winder FR	~		
General C	<u>Comments</u>						w winder RL	~		
Has a slight shudder when idling.							w winder RR	~		
							iew mirrors	~		
							(basic test only)	~		
							asic test only)	~		
						-	Number of keys 2			
Road Conditions During Test Driver						, I	Central locking			
Road Conditions During Test Drive: Dry								~		
Engine Timing Mechanism: Timing Chain							av. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:							sing camera			~
			11				ang camera			•
Inspected by: Donovan Matara Date: 15 Apr 2019										

I have read and understood this condition guide.

Name:

Signature: