

Report ID: 19,163,594 Version: 1 16 Apr 2019 Created:

Signature:

Make:	Toyota	Model:	Altezza	Body Style:	Sedan		Pass	Fail	N/A
Year:	2000	Registration:	LYZ486	Reg Expiry:	25 May 2019	Engine			
WoF Expiry:	06 Apr 2020	Odometer:	313,682 Kms	Good No:	19163594	Oil level	~		
VIN:	7A8H6390705039654	Next Service:	,	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~	•	
Key:	DPT	-0	D PT PT		DPT	Radiator / Hoses (visual)	~		
S = scratch						Transmission			<u> </u>
D = dent	GIE			The	ED DPT	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint defe C = crack				+	PT P	Clutch	~		
P = pin dent	Ho					CV joints	~		
* = decals	PT PIK			AL.	ELIP PT	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs		D PT D PT		Т	Performance	~		
		Note: som	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
	pection Comments						•	ofture	
Bonnet stay missing , R/Fog lamp cracked & N/W , I/R Taillight cracked , w/Screen chip x 1 , Roof rail moulding Missing x 1 , Aerial mast missing,						Tyres (lowest observed tread depth of tyres) Left front 7.0			
Wilssing X 1	, Achai mast missing,					Right front	7.	-	mm
						Left rear	7.		mm
								mm	
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments					Spare	Yes			
Oil seepage lower engine area & Diff Area,						Suspension			
		ili Alca,				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Poor						Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Poor					Indicators	~		
Panels						Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Ganaral	omments]	Window winder FR	~		
General Comments Cant Read lube sticker,					Window winder RL	~		<u> </u>	
						Window winder RR	~		<u> </u>
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Tes	t Drive:	Dry			Central locking		~	
Enging Ti	ming Mechanism	Camboli				Remote locking			~
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 293,064						Sat. Nav. (basic test only)			~
Evidence	oi cam Belt Replac	ernent: Y	es	Kms: 29	93,064	Reversing camera			~
Inspected by: Chris Buckley Date: 16 Apr 2019									

I have read and understood this condition guide.

Name: