

Report ID: 19,163,797 Version: 1 16 Apr 2019 Created:

Make:	Holden	Model:	Captiva 5	Body Style:	SUV		Pass	Fail	N/A
Year:	2009	Registration:	EYJ800	Reg Expiry:	30 Jul 2019	Engine			
WoF Expiry:		Odometer:	278,802 Kms	Good No:	19163797	Oil level	~		
VIN:	KL3DD26GJ8B200124	Next Service:		Service Histor	y: No	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty		с I 1	<b>D</b>	1 12 11 1	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			[
						Performance	~		
Key:	sc	-0	S D			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s 6/6			The	EID C	Operation	~		
R = rust PT = paint def				r in	JHIH	Noise	~		
C = crack				+		Clutch	-		~
P = pin dent						CV joints	~		-
* = decals	sc 916			The	EII PR-	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs						Performance	~		
		Note: son	ne defects & blemishe	s may not be disr	laved in the diagram	Hand Brake		~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							 d denth	•	
Windscreen broken						Tyres (lowest observed tread depth of tyres)           Left front         4.0         mm			 
						Right front		.0	
						Left rear		.0	mm
						Right rear	5.0		mm mm
Conditions During Body Inspection: Dry						Spare	5.0 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
Left rear sway bar link worn						Suspension performance			
Leithear Sw						Steering performance		~	
						Shock absorbers	~	V	
							V		
						Air Conditioning / Heater			
Interior Comments						Electrical / Accessories	~		
drivers seat torn									1
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		
Panels						Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
General (	omments					Window winder FR	~		
General Comments Noise from steering rack near lock to be investigated						Window winder RL	~		
Hand brake						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)	-	~	
						Number of keys	1		1
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
Engine Ti	ming Mechanism:	Timing	Chain			Remote locking	~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Lviuence		ement. p		NIII <b>3</b> ,		Reversing camera			~
Inspecte	d by: Greg Morgan					Date: 16 Apr 20	19		
	, , , , , , , , , , , , , , , , , , , ,								

I have read and understood this condition guide.

Name: .....

Signature: .....