

Report ID: 19,164,360 Version: 1 17 Apr 2019 Created:

Make:	Audi	Model:	A4	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2007	Registration:	MBZ268	Reg Expiry:	18 Jul 2019	Engine				
WoF Expiry:	07 Dec 2019	Odometer:	149,373 Kms	Good No:	19164360	Oil level	~			
VIN:	WAUZZZ8E77A182492	Next Service:	0	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and t	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
	S SC				S SC	Performance	~			
Key:	L SSC L	-0	S D		330	Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R = rust	S SC			715	HILS	Operation	~			
PT = paint defe		FI		$\left(\left \right\rangle \right)$		Noise	~			
C = crack					SC	Clutch			~	
P = pin dent	HIC				세비	CV joints	~			
* = decals	ssc 916			- Jul		Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SC S P SC S SC S SC						Performance	~			
Dedulmen		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)			es)	
LR tail light cracked ,						Left front 3 mn				
						Right front		3	mm	
						Left rear		2	mm	
Conditions During Body Inspection: Dry						Right rear		2	mm	
Conditions During Body Inspection: Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
	-					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater	•			
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats Average						Head lights	~			
						Tail lights	~			
Carpets	Average						~			
Danala	Average					Dashboard warning lights	~			
Panels						Wipers (front & rear)	v v			
Dashboa	rd glove box	broken ,				Window winder FL	v v			
						Window winder FE	~ ~			
General Comments						Window winder RL	v v			
						Window winder RL Window winder RR	<i>v</i> <i>v</i>			
						Rear view mirrors	v v			
						Radio (basic test only)	<i>v</i> <i>v</i>			
						CD (basic test only)	<i>v</i> <i>v</i>			
						Number of keys				
						Central locking	1			
Road Conditions During Test Drive: Dry							-			
Engine Timing Mechanism: Unknown						Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~	
						Reversing camera			~	
Inspected	d by: Donovan Matar	а				Date: 17 Apr 20	19	_		
·						-				

I have read and understood this condition guide.

Name:

Signature: