



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,165,168
Version:	2
Created:	06 Sep 2019

Make:	Nissan	Body Style:	SUV
Model:	Murano	VIN:	7AT0DH74X19001239
Year:	2008	Odometer:	113,958 Kms
Road Conditions During Test Drive:	Dry		

Electrical		Cooling System		Exterior	
1	Battery	✓	55	Coolant Condition	✓
2	Headlights	✓	56	Performance	✓
3	Tail Lights	✓	57	Radiator/Hoses (visual)	✓
4	High Stop Light	✓	Suspension		
5	Front Right Indicators	✓	58	Suspension Performance	✓
6	Front Left Indicators	✓	59	Steering Performance	✓
7	Rear Right Indicators	✓	60	Shock Absorbers	✓
8	Rear Left Indicators	✓	Wheels and Tyres		
9	Reversing Lights	✓	61	Left Front	2 mm
10	Rear Reflectors	✓	62	Right Front	5 mm
11	Hazard Lights	✓	63	Left Rear	4 mm
12	Courtesy Lights	✓	64	Right Rear	6 mm
13	Dashboard Lights	✓	65	Spare	Yes
14	Dashboard Dimmer Switch	✓	66	Tools	✓
15	Number Plate Light	✓	Interior		
16	Dashboard Warning Lights	✓	67	AC Operation	✓
17	Speedo	✓	68	Heater Fan	✓
18	Odometer	✓	69	Seatbelts	✓
19	Rev Counter	✓	70	Horn	✓
20	Fuel Gauge	✓	71	Seat Heaters	✓
21	Wipers Front/Rear	✓	72	Sun Visors	✓
22	Window Opener FL	✓	73	Sun Visors Lights/Mirrors	✓
23	Window Opener FR	✓	74	Seats	Good
24	Window Opener RL	✓	75	Carpets	Good
25	Window Opener RR	✓	76	Panels	Good
26	Rear View Mirrors	✓	77	Dashboard	Good
27	Radio (Basic Test Only)	✓	Turners Certification Key:		
28	CD (Basic Test Only)	✓	✓ = Pass		
29	Boot Open Switch	✓	X = Fail		
				• = Not applicable for this vehicle	

Inspected by:	Ian Dunn	Date:	06 Sep 2019
I have read and understood this condition guide:			
Name:		Signature:	