

Report ID: 56,580 Version: 3 03 May 2019 Created:

Make:	Mazda	Model:	CX-7	Body Style:	SUV		Pass	Fail	N/A
Year:	2007	Registration:		Reg Expiry:	23 Jul 2019	Engine	r ass	1 011	
WoF Expiry:		Odometer:		Good No:					1
VIN:	02 May 2020	Next Service:	159,273 Kms	Service Histor	19165498	Oil level Smoke & fumes	~		
VIN.	JM0ER103100100170	Next Service.		Service Histor	y: No		~		
Note: This re	port is not a warranty					Performance	~ ~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or Noise									
	nical inspection prior to					Cooling System	<u> </u>		1
						Coolant condition	~		
Key:	SC		S S			Performance	~		
S = scratch	~	(0)		$ \pm (0) $	\checkmark	Radiator / Hoses (visual)	~		
						Transmission			
R = rust	sc PP				HIL	Operation	~		
PT = paint def	ect N	11				Noise	~		
C = crack						Clutch			~
P = pin dent	sc s dl				~HHS	CV joints	~		
* = decals				70		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	SC S	C	S		S	Performance	~		
Body Insi	pection Comments	Note: som	ne defects & blemisl	nes may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread depth of tyres)			
						Left front	3.	0	mm
Right front							3.	0	mm
						Left rear	3.	0	mm
Conditions During Body Inspection: Dry						Right rear		3.0 mm	
Conditions During Body Inspection: Dry						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
	-					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Operation 🖌			
Casta	Good					Head lights			1
Seats							~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	3000					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Concert						Window winder FR	~		<u> </u>
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry Central locking									
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			V
							1		
Inspecte	d by: Scott					Date: 18 Apr 20	19		

I have read and understood this condition guide.

Name:

Signature: