

Report ID: 19,165,684 Version: 1 18 Apr 2019 Created:

| Make: | Toyota | Model: | Hilux | Body Style: | Utility | | Pass | Fail | N/A |
|---|---|----------------|--------------|----------------|-------------|------------------------------|------|------------|----------|
| Year: | 2014 | | HUN620 | Reg Expiry: | 15 Jun 2019 | Engine | | | |
| WoF Expiry: | | Odometer: | 71,068 Kms | Good No: | 19165684 | Oil level | ~ | | |
| VIN: | MR0EZ12G404158671 | | , | Service Histor | | Smoke & fumes | ~ | | |
| | | | 75,000 kms | | . 105 | Performance | ~ | | |
| | port is not a warranty | | | | | Noise | ~ | | |
| | a guide only. Conside sting undertaken. The | | | | | Cooling System | v | | |
| | ical inspection prior to | | | | | Coolant condition | ~ | | <u> </u> |
| | | | | | | Performance | | | |
| Key: | D | -0 | SD D | | S D | Radiator / Hoses (visual) | ~ | | |
| S = scratch | Sec | 20 | M | 10/2 | \sim | Transmission | ~ | | |
| D = dent | | | | | HIDP | | | | 1 |
| R = rust | - MIP | | | 10 | | Operation Noise | ~ | | |
| PT = paint defect C = crack | | | | | | Clutch | ~ | | |
| C = Crack P = pin dent | Ho | | | - | | | ~ | | |
| * = decals | sc db | | | | | CV joints | | | ~ |
| SC = stone chips | | | | | | Wheel bearings | ~ | | |
| W = significant scuffs D S D S | | | | | | Brakes | | | |
| | | | | | | Performance | ~ | | |
| Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram | | | | | | Hand Brake | | (· | Ļ |
| Hole in tuff deck | | | | | | Tyres (lowest observed tread | | | |
| Canopy and driver door seals damage | | | | | | Left front | 6 | | mm |
| | | | | | | Right front | e | | mm |
| | | | | | | Left rear | e | 5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6 mm | | |
| | | | | | | Spare | | Yes | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | Suspension | | | | |
| Rear wheel Underbody | drive surface rust | | | | | Suspension performance | ~ | | |
| | ring fluid low | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| Interior Comments | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Carpets | wear and t | ear | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | < | | |
| Dashboa | rd Average | | | | | Wipers (front & rear) | < | | |
| Dashboa | ra | | | | | Window winder FL | ~ | | |
| _ | | | | | | Window winder FR | ~ | | |
| <u>General (</u> | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Con | ditions During Test | t Drive: | Dry | | | Central locking | ~ | | |
| | | | • | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Cambelt | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | 10 | Kms: | | Reversing camera | | | ~ |
| | | | | | | | | | |
| Inspecte | Inspected by: Ca Thach Date: 18 Apr 2019 | | | | | | | | |
| I have read | and understood th | is condition o | juide. Name: | | | Signature: | | | |