

Report ID: 19,166,717 Version: 2 03 Jul 2019 Created:

Make:	Mercedes-Benz	Model:	A180	Body Style:	Hatchback			Pass	Fail	N/A	
Year:	2011	Registration: LWD506 Reg Expiry: 05 Jun 2019				Enc	jine				
WoF Expiry:	17 Sep 2019	Odometer: 33,317 Kms Good No: 19166717					il level	~			
VIN:	WDD1690322J965848	Next Service:		Service Histor	y: No	Sr	noke & fumes	~			
					-	I Pe	erformance	~			
Note: This report is not a warranty							oise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition				
						. —	erformance	<u>、</u>			
Key:		-0			s		adiator / Hoses (visual)	~			
S = scratch							nsmission	•			
D = dent	s sc			The	EID S		peration	~			
R = rust				10	JHIH		oise	~			
PT = paint defects C = crack					SC		lutch	•		~	
P = pin dent	Ho						V joints	~		•	
* = decals	sc pip			AL-			/heel bearings	~			
SC = stone chips						Brakes					
W = significant scuffs W						Performance					
		Notocom									
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							and Brake		. (-)	
						Tyres (lowest observed tread depth of tyres)				-	
							Left front		4 n		
							Right front		4 m		
L							Left rear		4 mr		
Conditions During Body Inspection: Wet							Right rear			4 mm	
		un at lu au a sti s	n Commonte			<u> </u>	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments							pension				
Front whee	l drive						uspension performance	~			
							eering performance	~			
						Sł	nock absorbers	~			
						Air	Conditioning / Heater				
						0	peration	~			
Interior Comments						Electrical / Accessories					
Seats	Good					Н	ead lights	~			
Carpote	Good					Ta	ail lights	~			
Carpets						In	dicators	~			
Panels	Good					Da	ashboard warning lights	~			
	Good					W	'ipers (front & rear)		~		
Dashboa	ra					W	indow winder FL	~			
						W	/indow winder FR	~			
	<u>Comments</u>					W	/indow winder RL	~			
Rear wiper	fail					W	/indow winder RR	~			
						Re	ear view mirrors	~			
						Ra	adio (basic test only)	~			
						CI	D (basic test only)	~			
						N	Number of keys		1		
Road Conditions During Test Drive: Wet						Ce	entral locking	~			
							emote locking	~			
Engine Timing Mechanism: Timing Chain							at. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: Not Applicable Kms:							eversing camera			~	
L											
Inspected by: Xinghui Lin Date: 03 Jul 2019											

I have read and understood this condition guide.

Name:

Signature: