

Basic Vehicle Condition Guide

Report ID: 19,166,793


Version: 3

Created: 28 May 2019

Make: Model: FIT Honda **Body Style:** Hatchback Year: 2004 Registration: GSD763 Reg Expiry: 31 Dec 2019 **Odometer:** WoF Expiry: 09 May 2020 166,580 Kms **Good No:** 19166793 VIN: 7AT08G2YX13031210 Next Service: 125138 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Audio antenna damaged

Stone chips on front windscreen (repaired)

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

Front wheel drive

| <u>Interior Comments</u> | | | |
|--------------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Actual odometer is 116654 KM

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

28 May 2019 Inspected by: **Bobby Zhong** Date:

Name:

| Create | d: 28 | 3 May 2 | 2019 |
|------------------------------|-----------------|---------|-------------------------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ~ | | |
| Performance | \(\times \) | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | ~ | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | ı | | 1 |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | ~ | | |
| Brakes | | | |
| Performance | ~ | | |
| Hand Brake | ~ | | |
| Tyres (lowest observed tread | d depth | of tyre | es) |
| Left front | I | | mm |
| Right front | | 2 | mm |
| Left rear | | 2 | mm |
| Right rear | 2 | | mm |
| Spare | • | Yes | |
| Suspension | | | |
| Suspension performance | V | | |
| Steering performance | <i>y</i> | | |
| Shock absorbers | \(\triangle \) | | |
| Air Conditioning / Heater | | | |
| Operation | ~ | | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | ~ | | |
| Window winder FL | ~ | | |
| Window winder FR | V | | |
| Window winder RL | ~ | | |
| Window winder RR | ~ | | |
| Rear view mirrors | V | | |
| Radio (basic test only) | | | |
| | <i>V</i> | | |
| CD (basic test only) | ļ - | | |
| Number of keys | 1 | | |
| Central locking | <i>V</i> | | |
| Remote locking | | | _ |
| Sat. Nav. (basic test only) | | | <i>V</i> |
| Reversing camera | | | \ \bullet \(\bullet \) |

Signature: