

Basic Vehicle Condition Guide

Report ID: 19,174,165


Version: 2

08 May 2020

Make: Model: Holden Cruze **Body Style:** Wagon Year: 2017 Registration: KJT376 Reg Expiry: 15 Jun 2020 WoF Expiry: **Odometer:** 16 Feb 2021 95,009 Kms **Good No:** 19174165 VIN: KL3JA35MJGK352552 **Next Service:** 95300 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Windscreen stone chip not in CVA

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Gearbox oil leak

Interior Comments			
Seats	Marks on seats		
Carpets	Good		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

John Lindsay

Evidence of Cam Belt Replacement: No Kms:

Creater	u. 00	o ividy 2	.020
	Pass	Fail	N/A
Engine	•	•	
Oil level	~		
Smoke & fumes	\(\triangle \)		
Performance	~		
Noise	~		
Cooling System	•	•	
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission			•
Operation	~		
Noise	V V		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4	4	mm
Right front	4		mm
Left rear	4		mm
Right rear	5		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	>		
Electrical / Accessories			
Head lights	'		
Tail lights	~		
Indicators	~		
Dashboard warning lights	V V V V V V V		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~

I have read and understood this condition guide.

Name:

Signature:

08 May 2020

Reversing camera