

Basic Vehicle Condition Guide

Report ID: 19,175,939


Version: 1

23 Jan 2020 Created:

Make: Model: Hyundai lload **Body Style:** Van Year: 2013 Registration: HED903 Reg Expiry: 28 Feb 2020 WoF Expiry: **Odometer:** 19 Nov 2020 131,062 Kms **Good No:** 19175939 VIN: KMFWBX7KLDU59869 **Next Service:** 139000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Aerial hole on roof Vent on roof

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Commen | <u>ts</u> |
|-----------------|---------------------|
| Seats | Marks on seats |
| Carpets | Drivers carpet worn |
| Panels | Good |
| Dashboard | Scratches |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: John Lindsay

| Created: 23 Jan 2020 | | | | | |
|--|---|---------|-----|--|--|
| | Pass | Fail | N/A | | |
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | ~ | | | | |
| Performance | \(\triangle \) | | | | |
| Noise | ~ | | | | |
| Cooling System | Cooling System | | | | |
| Coolant condition | ~ | | | | |
| Performance | ~ | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Transmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | ~ | | | | |
| CV joints | \(\times \) | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | | | | |
| Performance | ~ | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread | depth | of tyre | es) | | |
| Left front | | 8 | | | |
| Right front | | 8 | mm | | |
| Left rear | | 8 | mm | | |
| Right rear | | 8 | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| | | | _ | | |
| Suspension performance | ~ | | | | |
| Suspension performance Steering performance | V | | | | |
| | > > > | | | | |
| Steering performance | VVV | | | | |
| Steering performance Shock absorbers | \(\times \) | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater | \(\times \) | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation | V V V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories | V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights | V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights | V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators | V V V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights | V V V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) | V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL | V V V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR | V V V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL | V V V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR | V V V | | v | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RL Window winder RR Rear view mirrors | V V V | | V | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) | V V V V V V V V V V V V V V V V V V V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) | V V V V V V V V V V V V V V V V V V V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys | V V V V V V | | | | |
| Steering performance Shock absorbers Air Conditioning / Heater Operation Electrical / Accessories Head lights Tail lights Indicators Dashboard warning lights Wipers (front & rear) Window winder FL Window winder FR Window winder RR Rear view mirrors Radio (basic test only) CD (basic test only) Number of keys Central locking | V V V V V V | | V V | | |

I have read and understood this condition guide.

Name:

Signature:

23 Jan 2020

Date: