

Report ID: 19,176,919 Version: 2 15 Nov 2019 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A	
Year:	2013	Registration:	HAK499	Reg Expiry:	14 May 2020	Engine			,	
	17 Aug 2020	Odometer:	116,510 Kms	Good No:	19176919	Oil level	~			
VIN:	MR0FZ22G401193724			Service Histor		Smoke & fumes	~			
						Performance	~			
	port is not a warranty		с I II	D		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition				
						Performance	~			
Key: SD SD PT SD						Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent D R SC W						Operation 🖌				
R = rust D HOC W PT = paint defect C = crack S D SC						Noise	~			
						Clutch	~			
P = pin dent						CV joints	~			
*=decals SC 00						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs S S D S D R						Performance	~			
		Note: son	ne defects & blemishes	may not be disp	laved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Tyres (lowest observed treat		oftyre	es)	
Right sill paint defect Left running board dented									mm	
Aerial hole on roof						Right front		1	mm	
						Left rear		5	mm	
Conditions During Rody Inspection						Right rear	5 mm		-	
Conditions During Body Inspection: Dry						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Centre console lid bracket broken						Suspension performance	~			
Driver handle on a pillar broken						Steering performance	~			
Roof lining above doors worn Left front cupholder broken						Shock absorbers	~			
Clutch pedal cover missing Left front door doesn't lock with remote or key						Air Conditioning / Heater	•			
Left front d	bor doesn't lock with re	mote of key				Operation	~			
Interior Comments						Electrical / Accessories				
Seats driver seat worn						Head lights	~			
	duis con no of	halaa				Tail lights	~			
Carpets	driver mat	noies				Indicators	~			
Panels	Average					Dashboard warning lights	~			
						Wipers (front & rear)	~			
Dashboa	rd glovebox	wont close				Window winder FL	~			
					J	Window winder FR	~			
General Comments						Window winder RL	~			
Front underbody oxidisation						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2	I	1	
Road Conditions During Test Drive: Dry						Central locking	~			
						Remote locking		~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~	
L										
Inspected by: Kyle Mills-Brown Date: 15 Nov 2019										

I have read and understood this condition guide.

Name:

Signature: