

## **Basic Vehicle Condition Guide**

Report ID: 19,177,687


Version: 3

16 Jan 2020 Created:

Make: Model: Hyundai lload **Body Style:** Van Year: 2016 Registration: KCM763 Reg Expiry: 28 Dec 2019 WoF Expiry: **Odometer:** 29 Sep 2020 77,740 Kms **Good No:** 19177687 VIN: KMFWBX7KMHU8591 **Next Service:** 70000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

L side door not opening

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy

Interior Comments			
Seats	L F split		
Carpets	Average		
Panels	Average		
Dashboard	Good		

	_
General	Comments

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

	Pass	Fail	N/A			
Engine	. 433	, ull	14/74			
Oil level						
Smoke & fumes	•					
Performance	V V					
Noise	•					
Cooling System						
Coolant condition	./					
Performance	./					
Radiator / Hoses (visual)	•					
Transmission						
Operation	./					
Noise	./					
Clutch	•					
CV joints Wheel bearings	V					
Wheel bearings   Brakes						
Performance	.,		l			
Hand Brake						
	l dopth	of ture	)c)			
Tyres (lowest observed tread depth of tyres)  Left front 5.2 mm						
		.2	mm			
Right front Left rear	4.2		mm			
		.5	mm			
Right rear	3	.9	mm			
Spare Yes						
Suspension performance						
Suspension performance Steering performance						
Shock absorbers	<i>V</i>					
	•					
Air Conditioning / Heater						
Operation  Electrical / Accessories	•					
Head lights	-					
Tail lights	<i>V</i>					
Indicators	-					
Dashboard warning lights	<i>V</i>					
Wipers (front & rear) Window winder FL	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
Window winder FL Window winder FR						
Window winder FR Window winder RL	<b>'</b>					
Window winder RL Window winder RR						
Rear view mirrors	<i>V</i>					
Radio (basic test only)	· ·					
CD (basic test only)	_					
Number of keys	2					
Central locking	1					
Remote locking	-					
Sat. Nav. (basic test only)			<b>'</b>			
Reversing camera			<u> </u>			
Date: 20 Nov 2019						

I have read and understood this condition guide.

Stuart Melbourne

Name: .....

Signature: .....

20 Nov 2019