

Basic Vehicle Condition Guide

Report ID: 19,179,305


Version: 2

Created: 13 Nov 2019

Make: Model: Holden Colorado **Body Style:** Utility Year: 2013 Registration: **GUN881** Reg Expiry: 19 Dec 2019 WoF Expiry: **Odometer:** 20 Mar 2020 156,832 Kms **Good No:** 19179305 VIN: MMU148DH0DH6340 Next Service: 160,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Stone chips front screen Badge missing from tailgate

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments			
Seats	Drivers seat ripped		
Carpets	Average		
Panels	Average		
Dashboard	Cover missing from USB port		

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Murray Craig Date: 04 Nov 2019

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	v		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	\(\times \)		
CV joints	~		
Wheel bearings	~		
Brakes	•		
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	7	.0	mm
Right front	8.0		mm
Left rear	7.0		mm
Right rear	6.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			1
Operation	~		
Electrical / Accessories			
Head lights	~		Ι
Tail lights	~		
Indicators			
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	V		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		1
Central locking	2 V		
Remote locking	•		\vdash
Sat. Nav. (basic test only)			-
-			.,
Reversing camera			<i>V</i>

Signature: