

Report ID: 19,180,311 Version: 3 04 Nov 2019 Created:

Make:	Nissan	Model:	Navara	Body Style:	Utility		Pass	Fail	N/A
Year:	2008	Registration:	FKW978	Reg Expiry:	08 Mar 2020	Engine	1		L
WoF Expiry:	18 Nov 2020	Odometer:	256,488 Kms	Good No:	19180311	Oil level	~		
VIN:	JN1CPUD22A0020459	Next Service:	266000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
	S SC SC		S D S D SC	SC	S D	Performance	~		
Key:	1350 [[3	-0	30 3030			Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission	Transmission		
R = rust SW A SW						Operation	~		
PT = paint defe	ect NP					Noise	~		
C = crack				TTY .	D W	Clutch	~		
P = pin dent	S D SC				24116	CV joints	~		
n = decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W = Significan	s sc sc		P SC W S P SC V	v SC	S P W	Performance	~		
Body Insr	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
L/H tail light cracked.						Tyres (lowest observed tread depth of tyres)			
Aerial broken.						Left front	2.0 mm		mm
						Right front	2	.0	mm
						Left rear	8	.0	mm
Conditions During Body Inspection: Dry						Right rear	9.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
Steering perform						Steering performance	~		
SI						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	on 🖌		
Interior Comments rip on drivers seat. I/f seat belt webbing damaged						Electrical / Accessories			
Seats	rip on driv	ers seat. I/f seat I	belt webbing damaged	1		Head lights	~		
Carpote	holes on d	rivers side.				Tail lights	~		
Carpets						Indicators	~		
Panels	console bo	oot loose.				Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
Dashboa	ra					Window winder FL	~		
	-					Window winder FR	~		
General Comments 4x4 manual d/cab ute.						Window winder RL	~		
4x4 manual	d/cab ute.					Window winder RR	~		
						Rear view mirrors			~
						Radio (basic test only)	~		
						CD (basic test only)		~	
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
Remote locking									~
						Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Daryll Timms Date: 25 Oct 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....