

Report ID: 19,180,535 Version: 2 14 Nov 2019 Created:

Make:	Ford	Model:	Mondeo	Body Style:	Wagon		Pass	Fail	N/A
Year:	2015	Registration:	JMA57	Reg Expiry:	29 Nov 2019	Engine			L
WoF Expiry:		Odometer:	239,348 Kms	Good No:	19180535	Oil level	~		
VIN:	WF0FXXWPCFFS2160	Next Service:		Service Histor	y: Yes	Smoke & fumes	~		
					-	Performance	~		
	port is not a warranty	unting is mode	for one and miles as	Dauta hava nat	heen discontinuing or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	D SC S SC			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SC W			TIN		Operation	~		
R = rust PT = paint def				$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	110				게	CV joints	~		-
* = decals	DSC 916			-Jul-	ELD SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC SC SC D						Performance	~		
Dealerteen		Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	d depth	of tyre	es)
Stone chips front screen. Cig burn hole in drivers seat								mm	
						Right front		.0	mm
						Left rear		.0	mm
Conditions During Body Inspection: Wet						Right rear		.0	mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			1
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
	Good					Tail lights	~		
Carpets	0000					Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
	1				I	Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
NAV SD CARD MISSING						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2	1	
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)		~	
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera	~		
· · ·								1	<u> </u>
Inspected by: Brian Hill Date: 04 Nov 2019									

I have read and understood this condition guide.

Name:

Signature: