

Report ID: 19,181,850 Version: 3 31 Oct 2019 Created:

| Make: | Suzuki | Model: | Swift | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|--|----------------------|------------------------|---------------------------------------|----------------------|------------------------------|------------|---------|----------|
| Year: | 2015 | Registration: | HWK771 | Reg Expiry: | 10 Feb 2020 | Engine | • | | · |
| WoF Expiry: | 04 Feb 2020 | Odometer: | 32,761 Kms | Good No: | 19181850 | Oil level | ~ | | |
| VIN: | JSAFZC82S00312570 | Next Service: | 41,000kms | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty a quide only Conside | eration is made | for age and mileage | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and t | his can be arranged fo | or an additional o | charge. | Coolant condition | ~ | | |
| | S P W | | C CD | | | Performance | ~ | | |
| Key: | SP | -0 | S SP | | | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | Transmission | | | |
| D = dent R = rust | | | | 715 | HILS | Operation | ~ | | |
| PT = paint defe | | FI | | $\left(\left \right\rangle \right)$ | | Noise | ~ | | |
| C = crack | | | | | SC | Clutch | | | ~ |
| P = pin dent | HIP | | | | 74116 | CV joints | ~ | | |
| * = decals | sc 916 | | | | ALD S | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs S S S S S S | | | | | | Performance | ~ | | |
| Body Incr | oction Commonts | Note: son | ne defects & blemishes | s may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread | l depth | of tyre | 1 2S) |
| | | | | | | | | | mm |
| | | | | | | Right front | | | mm |
| | | | | | | Left rear | | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 4.0 mm | | mm |
| Conditions During Body inspection. Dry | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| OK. | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| Shock absorb | | | | | | | ~ | | |
| | Air Conditioning / Heater | | | 1 | | | | | |
| | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | Average | | | | | Indicators | ~ | | |
| Panels | cargo shel | f string holder m | issing. | | | Dashboard warning lights | ~ | | |
| | Augrage | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd Average | | | | | Window winder FL | ~ | | |
| | 1 | | | | | Window winder FR | ~ | | |
| General Comments | | | | | | Window winder RL | ~ | | |
| Nice little h | atch. | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 1 | | |
| Road Con | ditions During Test | t Drive | Dry | | | Central locking | ~ | | |
| Remote locking | | | | | | | ~ | | |
| Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only) | | | | | | | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera | | | | | | | | | ~ |
| Inspected by: Daryll Timms Date: 11 Oct 2019 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: