



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

| | |
|------------|-------------|
| Report ID: | 19,195,984 |
| Version: | 2 |
| Created: | 28 Aug 2020 |

| | | | |
|------------------------------------|--------|-------------|-------------------|
| Make: | Toyota | Body Style: | Hatchback |
| Model: | Prius | VIN: | 7AT0H637X20052167 |
| Year: | 2017 | Odometer: | 10,480 Kms |
| Road Conditions During Test Drive: | Dry | | |

| Electrical | | 30 | Fuel Flap Release | ✓ | Cooling System | | 55 | Coolant Condition | ✓ | Exterior | | 78 | Under Carriage | Good | | |
|------------|--------------------------|----|------------------------|----------------------------------|---|------------------|--|--|------------------------|---|--|----------------------------|------------------|------------|------------|------|
| 1 | Battery | ✓ | 31 | Reversing Camera | ✓ | 56 | Performance | ✓ | 79 | Sun Roof Operation | | • | | | | |
| 2 | Headlights | ✓ | 32 | USB Port | • | 57 | Radiator/Hoses (visual) | ✓ | 80 | Front Windscreen (no chips) | Good | | | | | |
| 3 | Tail Lights | ✓ | 33 | Window Lock Switch | ✓ | Suspension | | 58 | Suspension Performance | ✓ <td>81</td> <td>Back Windscreen (no chips)</td> <td>Good</td> | 81 | Back Windscreen (no chips) | Good | | | |
| 4 | High Stop Light | ✓ | Transmission and Drive | | 34 | Operation | ✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>82</td><td>Side Windows (no chips)</td><td>Good</td></th> | 59 | Steering Performance | ✓ <td>82</td> <td>Side Windows (no chips)</td> <td>Good</td> | 82 | Side Windows (no chips) | Good | | | |
| 5 | Front Right Indicators | ✓ | 35 | Noise | ✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<td>83</td><td>Front Wiper Blades</td><td>Good</td></th> | 60 | Shock Absorbers | ✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td> | 83 | Front Wiper Blades | Good | | | | | |
| 6 | Front Left Indicators | ✓ | 36 | Clutch | • | Wheels and Tyres | | 61 | Left Front | 6 | mm | 84 | Rear Wiper Blade | Good | | |
| 7 | Rear Right Indicators | ✓ | 37 | CV Joints | ✓ <td>62</td> <td>Right Front</td> <td>6</td> <td>mm</td> <td>63</td> <td>Left Rear</td> <td>6</td> <td>mm</td> <td>85</td> <td>R/H Mirror</td> <td>Good</td> | 62 | Right Front | 6 | mm | 63 | Left Rear | 6 | mm | 85 | R/H Mirror | Good |
| 8 | Rear Left Indicators | ✓ | 38 | Wheel Bearing | ✓ <td>64</td> <td>Right Rear</td> <td>6</td> <td>mm</td> <td>65</td> <td>Spare</td> <td>N/A</td> <td>86</td> <td>L/H Mirror</td> <td>Good</td> | 64 | Right Rear | 6 | mm | 65 | Spare | N/A | 86 | L/H Mirror | Good | |
| 9 | Reversing Lights | ✓ | 39 | Wheel Balance | ✓ <td>66</td> <td>Tools</td> <th>✓</th> <td>87</td> <td>L/F Guard</td> <td>Good</td> | 66 | Tools | ✓ | 87 | L/F Guard | Good | | | | | |
| 10 | Rear Reflectors | ✓ | 40 | Gearbox (Manual) | • | Interior | | 67 | AC Operation | ✓ <td>88</td> <td>R/F Guard</td> <td>Good</td> | 88 | R/F Guard | Good | | | |
| 11 | Hazard Lights | ✓ | 41 | Engine Timing | Timing Chain | 68 | Heater Fan | ✓ <td>69</td> <td>Seatbelts</td> <th>✓<td>89</td><td>L/H Doors</td><td>Good</td></th> | 69 | Seatbelts | ✓ <td>89</td> <td>L/H Doors</td> <td>Good</td> | 89 | L/H Doors | Good | | |
| 12 | Courtesy Lights | ✓ | 42 | Evidence of Cam Belt Replacement | Not Applicable | 70 | Horn | ✓ <td>71</td> <td>Seat Heaters</td> <td>•</td> <td>90</td> <td>R/H Doors</td> <td>Good</td> | 71 | Seat Heaters | • | 90 | R/H Doors | Good | | |
| 13 | Dashboard Lights | ✓ | 43 | Replaced at (odometer reading) | | 72 | Sun Visors | ✓ <td>73</td> <td>Sun Visors Lights/Mirrors</td> <th>✓<td>91</td><td>L/H Sill</td><td>Good</td></th> | 73 | Sun Visors Lights/Mirrors | ✓ <td>91</td> <td>L/H Sill</td> <td>Good</td> | 91 | L/H Sill | Good | | |
| 14 | Dashboard Dimmer Switch | • | Brakes | | 44 | Front Brakes | ✓ <td>74</td> <td>Seats</td> <td>Good</td> <td>92</td> <td>R/H Sill</td> <td>Good</td> | 74 | Seats | Good | 92 | R/H Sill | Good | | | |
| 15 | Number Plate Light | ✓ | 45 | Rear Brakes | ✓ <td>46</td> <td>Handbrake</td> <th>✓<td>75</td><td>Carpets</td><td>Good</td><td>93</td><td>Boot/Tail Gate</td><td>Good</td></th> | 46 | Handbrake | ✓ <td>75</td> <td>Carpets</td> <td>Good</td> <td>93</td> <td>Boot/Tail Gate</td> <td>Good</td> | 75 | Carpets | Good | 93 | Boot/Tail Gate | Good | | |
| 16 | Dashboard Warning Lights | ✓ | Keys and Locking | | 47 | Central Locking | ✓ <td>76</td> <td>Panels</td> <td>Good</td> <td>94</td> <td>Front Bumper</td> <td>Good</td> | 76 | Panels | Good | 94 | Front Bumper | Good | | | |
| 17 | Speedo | ✓ | 48 | Remote Locking | ✓ <td>49</td> <td>Number of Keys</td> <td>2</td> <td>77</td> <td>Dashboard</td> <td>Good</td> <td>95</td> <td>Rear Bumper</td> <td>Good</td> | 49 | Number of Keys | 2 | 77 | Dashboard | Good | 95 | Rear Bumper | Good | | |
| 18 | Odometer | ✓ | Engine | | 50 | Oil Level | ✓ <td>78</td> <td>Seats</td> <td>Good</td> <td>96</td> <td>Roof</td> <td>Good</td> | 78 | Seats | Good | 96 | Roof | Good | | | |
| 19 | Rev Counter | ✓ | 51 | Smokes and Fumes | ✓ <td>52</td> <td>Performance</td> <th>✓<td>79</td><td>Carpets</td><td>Good</td><td>97</td><td>Bonnet</td><td>Good</td></th> | 52 | Performance | ✓ <td>79</td> <td>Carpets</td> <td>Good</td> <td>97</td> <td>Bonnet</td> <td>Good</td> | 79 | Carpets | Good | 97 | Bonnet | Good | | |
| 20 | Fuel Gauge | ✓ | 53 | Noise | ✓ <td>54</td> <td>Starter Motor</td> <th>✓<td>80</td><td>Panels</td><td>Good</td><td>98</td><td>Fuel Cap</td><th>✓</th></th> | 54 | Starter Motor | ✓ <td>80</td> <td>Panels</td> <td>Good</td> <td>98</td> <td>Fuel Cap</td> <th>✓</th> | 80 | Panels | Good | 98 | Fuel Cap | ✓ | | |
| 21 | Wipers Front/Rear | ✓ | | | | | | | 81 | Dashboard | Good | 99 | Mud Flaps | ✓ | | |
| 22 | Window Opener FL | ✓ | | | | | | | 82 | | | 100 | WOF | ✓ | | |
| 23 | Window Opener FR | ✓ | | | | | | | 83 | | | | | | | |
| 24 | Window Opener RL | ✓ | | | | | | | 84 | | | | | | | |
| 25 | Window Opener RR | ✓ | | | | | | | 85 | | | | | | | |
| 26 | Rear View Mirrors | ✓ | | | | | | | 86 | | | | | | | |
| 27 | Radio (Basic Test Only) | ✓ | | | | | | | 87 | | | | | | | |
| 28 | CD (Basic Test Only) | • | | | | | | | 88 | | | | | | | |
| 29 | Boot Open Switch | ✓ | | | | | | | 89 | | | | | | | |

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

| | | | |
|---------------|----------------|-------|-------------|
| Inspected by: | Lewis Dolamore | Date: | 28 Aug 2020 |
|---------------|----------------|-------|-------------|

I have read and understood this condition guide:

| | | | |
|-------|--|------------|--|
| Name: | | Signature: | |
|-------|--|------------|--|