

Basic Vehicle Condition Guide

Report ID: 19,225,276


Version: 5

Created: 30 Apr 2020

Make: Model: Hyundai Getz **Body Style:** Hatchback Year: 2008 Registration: **ERY917** Reg Expiry: 14 Jun 2020 WoF Expiry: **Odometer: Good No:** 06 Mar 2021 179,806 Kms 19225276 VIN: KMHBU51BR9U84837 Next Service: 189,700kms Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

L/H sill scratched & dented.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

OK.

Interior Comments			
Seats	Average		
Carpets	Average		
Panels	Drivers door handle chrome peeling.		
Dashboard	Average		

General Comments

Nice little hatch.

Inspected by:

Fuel lever knob missing.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Daryll Timms

Evidence of Cam Belt Replacement: No Kms:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	<i>V V</i>		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	7.0 mm		
Right front	7.0		mm
Left rear	5.0		mm
Right rear	3.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			•
Operation	~		
Electrical / Accessories			
Head lights	1		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		1
Central locking	·		
Remote locking	~		
Sat. Nav. (basic test only)			V
Reversing camera			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
neversing camera			

30 Jan 2020

Signature:

Date: