



Turners Certified 100 Point Check

Notes: This report is not a warranty.

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

Report ID:	19,226,642
Version:	1
Created:	22 Jan 2020

Make:	Nissan	Body Style:	Hatchback
Model:	Note	VIN:	7AT0DH79X20075344
Year:	2017	Odometer:	95,821 Kms
Road Conditions During Test Drive:	Dry		

Electrical		30	Fuel Flap Release	✓	Cooling System		78	Under Carriage	Good	<div>Turners Certification Key:</div> <div>✓ = Pass</div> <div>✗ = Fail</div> <div>• = Not applicable for this vehicle</div>										
1	Battery	✓	31	Reversing Camera	•	55	Coolant Condition	✓	79		Sun Roof Operation	•								
2	Headlights	✓	32	USB Port	•	56	Performance	✓	80		Front Windscreen (no chips)	Good								
3	Tail Lights	✓	33	Window Lock Switch	✓	57	Radiator/Hoses (visual)	✓	81		Back Windscreen (no chips)	Good								
4	High Stop Light	✓	Transmission and Drive		Suspension		58	Suspension Performance	✓		82	Side Windows (no chips)	Good							
5	Front Right Indicators	✓	34	Operation	✓	59	Steering Performance	✓	83		Front Wiper Blades	Good								
6	Front Left Indicators	✓	35	Noise	✓	60	Shock Absorbers	✓	84		Rear Wiper Blade	Good								
7	Rear Right Indicators	✓	36	Clutch	•	Wheels and Tyres		61	Left Front		7	mm								
8	Rear Left Indicators	✓	37	CV Joints	✓	62	Right Front	7	mm		87	L/F Guard	Good							
9	Reversing Lights	✓	38	Wheel Bearing	✓	63	Left Rear	3	mm		88	R/F Guard	Good							
10	Rear Reflectors	✓	39	Wheel Balance	✓	64	Right Rear	3	mm	89	L/H Doors	Good								
11	Hazard Lights	✓	40	Gearbox (Manual)	•	65	Spare	No	66	Tools	✓	90	R/H Doors	Good						
12	Courtesy Lights	✓	41	Engine Timing	Timing Chain	67	AC Operation	✓	68	Heater Fan	✓	91	L/H Sill	Good						
13	Dashboard Lights	✓	42	Evidence of Cam Belt Replacement	Not Applicable										69	Seatbelts	✓	92	R/H Sill	Good
14	Dashboard Dimmer Switch	✓	43	Replaced at (odometer reading)		70	Horn	✓	71	Seat Heaters	•	93	Boot/Tail Gate	Good						
15	Number Plate Light	✓	Brakes		Interior		72	Sun Visors	✓	73	Sun Visors Lights/Mirrors	✓	94	Front Bumper	Good					
16	Dashboard Warning Lights	✓	44	Front Brakes	✓	74	Seats	Good	75	Carpets	Good	95	Rear Bumper	Good						
17	Speedo	✓	45	Rear Brakes	✓	76	Panels	Good	77	Dashboard	Good	96	Roof	Good						
18	Odometer	✓	46	Handbrake	✓	78	Fuel Cap	✓	79	Mud Flaps	✓	80	WOF	✓						
19	Rev Counter	✓	Keys and Locking		47										Central Locking	✓	81	Fuel Cap	✓	
20	Fuel Gauge	✓	48	Remote Locking	✓										49	Number of Keys	1	82	Sun Roof Operation	•
21	Wipers Front/Rear	✓	Engine		50										Oil Level	✓	83	Back Windscreen (no chips)	Good	
22	Window Opener FL	✓	51	Smokes and Fumes	✓	52	Performance	✓	84	Side Windows (no chips)	Good									
23	Window Opener FR	✓	53	Noise	✓	54	Starter Motor	✓	85	Front Wiper Blades	Good									
24	Window Opener RL	✓	55	Performance	✓															
25	Window Opener RR	✓																		
26	Rear View Mirrors	✓																		
27	Radio (Basic Test Only)	✓																		
28	CD (Basic Test Only)	✓																		
29	Boot Open Switch	✓																		

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

Inspected by:	Daryll Timms	Date:	22 Jan 2020
---------------	--------------	-------	-------------

I have read and understood this condition guide:

Name:		Signature:	
-------	--	------------	--