

Report ID: 19,226,949 Version: 1 22 Jan 2020 Created:

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2013	Registration:	HCE245	Reg Expiry:	29 Mar 2020	Engine	1		I
WoF Expiry:	07 Oct 2020	Odometer:	152,457 Kms	Good No:	19226949	Oil level	~		
VIN:	KMFWBX7KLDU58207	Next Service:	163000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	S PT S PT	-01-	S PT	Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			I
D = dent R = rust				715	HIV	Operation	~		
PT = paint defe		F		$\left[\left(\right) \right]$		Noise	~		
C = crack					SC	Clutch	~		
P = pin dent	110				74114	CV joints	-		~
* = decals	sc 916			-No-	SD SD	Wheel bearings	~		
SC = stone chips						Brakes			I
W = significan			SD S			Performance	~		
Do al e luc -	notion Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments LR lens cracked						Tyres (lowest observed tread depth of tyr			es)
LR lens cracked								mm	
						Right front		7	mm
						Left rear		.5	mm
Conditions During Body Inspection: Dry					Right rear			mm	
Conditions During Body Inspection: Dry					Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
	Deer					Tail lights	~		
Carpets	Poor					Indicators	~		
Panels	Poor					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Poor					Window winder FL	~		
						Window winder FR	v		
General C	<u>Comments</u>					Window winder RL	-		~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		· ·	
						Number of keys	1		I
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	-		~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
L								1	1
Inspected by: Stuart Melbourne Date: 22 Jan 2020									

I have read and understood this condition guide.

Name:

Signature: