

Report ID: 19,240,088 Version: 2 11 Feb 2020 Created:

| Make: | Nissan | Model: | Tiida | Body Style: | Hatchback | | | Pass | Fail | N/A |
|--|---|---|------------------------|-------------------|-----------------------|--|----------------------------|------|------|-----|
| Year: | 2005 | Registration:HGZ124Reg Expiry:06 Mar 2020 | | Eng | Engine | | | | | |
| WoF Expiry: | 05 Aug 2020 | Odometer: | 240,120 Kms | Good No: | 19240088 | 0 | il level | ~ | | |
| VIN: | 7AT0DH78X12032925 | Next Service: | 243000 | Service Histor | y: No | Sr | moke & fumes | ~ | | |
| | | | | | | Pe | erformance | ~ | | |
| | port is not a warranty a guide only. Conside | eration is made | for age and mileage | Parts have not | been dismantled or | N | oise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | | |
| a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | C | oolant condition | ~ | | |
| | S SC | | S D SC S P SC | | SC | Pe | erformance | ~ | | |
| Key: | | = | 3030 3130 | 500- | | Ra | adiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Tra | nsmission | 1 | | |
| R = rust | s sc | | | 20 | E SD | 0 | peration | ~ | | |
| PT = paint def | ect NP | | | | 11111 | N | oise | ~ | | |
| C = crack | | | | | SC | C | lutch | | | ~ |
| P = pin dent | s sc dl | | | | 74116 | C | V joints | ~ | | |
| * = decals | | 10 | | 10 | SD SD | W | /heel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | | |
| W = significant scutts SC S S SC S D C SC S D C SC S D C SC | | | | | | Pe | erformance | ~ | | |
| Body Insr | pection Comments | Note: son | ne defects & blemishes | s may not be disp | layed in the diagram | н | and Brake | ~ | | |
| Rear bumper needs alignment , | | | | | | Tyres (lowest observed tread depth of tyres) | | | | 25) |
| | | | | | | Le | Left front 7 | | | mm |
| | | | | | | Ri | ight front | 7 | | mm |
| | | | | | | Le | Left rear | | 7 m | |
| Conditions During Body Inspection: Dry | | | | | | Ri | Right rear 7 | | 7 | mm |
| | | | | | | Sp | Spare Yes | | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | | |
| | | | | | | Su | uspension performance | ~ | | |
| | | | | | | St | teering performance | ~ | | |
| | | | | | | Sł | hock absorbers | ~ | | |
| | | | | | | Air | Air Conditioning / Heater | | | |
| | | | | | | 0 | peration | | ~ | |
| Interior Comments | | | | | | Ele | Electrical / Accessories | | | |
| Seats | drivers sea | t cracked , | | | | Н | ead lights | ~ | | |
| Comoto | wear and t | ear,minor stains | ,worn , | | | Tá | ail lights | ~ | | |
| Carpets | | | | | | In | dicators | ~ | | |
| Panels | middle coi | nsole lid cracked | , | | | D | ashboard warning lights | ~ | | |
| Deskte | Average | | | W | /ipers (front & rear) | ~ | | | | |
| Dashboa | | | | | | W | /indow winder FL | ~ | | |
| | - | | | | | W | /indow winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | W | /indow winder RL | ~ | | |
| | | | | | | W | /indow winder RR | ~ | | |
| | | | | | | Re | ear view mirrors | ~ | | |
| | | | | | | Ra | adio (basic test only) | ~ | | |
| | | | | | | C | D (basic test only) | ~ | | |
| | | | | | | Ν | Number of keys 1 | | | |
| Road Conditions During Test Drive: Dry | | | | | | C | entral locking | ~ | | |
| | - | · | - | | | Re | emote locking | | ~ | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sa | at. Nav. (basic test only) | | | ~ |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Re | eversing camera | | | ~ |
| las e | | | | | | | | 20 | | |
| Inspecte | d by: Donovan Matar | a | | | | | Date: 11 Feb 202 | 20 | | |

I have read and understood this condition guide.

Name:

Signature: