

Report ID: 19,244,325 Version: 2 Created: 04 Jun 2020

Make:	Volkswagen	Model:	Т5	Body Style:	Van		Pass	Fail	N/A
Year:	2014	Registration:	HPZ108	Reg Expiry:	24 Aug 2020	Engine			
WoF Expiry:	06 Nov 2020	Odometer:	149,158 Kms	Good No:	19244325	Oil level	~		
VIN:	WV1ZZZ7HZFH01064	Next Service:	153000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
	S D R PT SC W		S D R PT SC S D R P	TW	S D PT SC V	Performance	~		
Key:	13D MITS W	=		5(0)-	J J J J J J J J J J J J J J J J J J J	Radiator / Hoses (visual)	~		
S = scratch						Transmission	Transmission		
R = rust SW AR SPT						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	S PT SC				74116	CV joints	~		
= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
S D R SC W S PT P SC V S D R PT SC W S D R SC W						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
Rear wiper cap missing						Tyres (lowest observed trea	ad depth of tyres)		
Tailgate badge missing						Left front	4.0 mm		mm
						Right front	3.	.0	mm
						Left rear	8	.0	mm
Conditions During Body Inspection: Dry						Right rear	8	.0	mm
						Spare No			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Rear left wheel hub cover missing Piece steering wheel cover missing						Suspension performance	~		
Piece steeri	ng wheel cover missing					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Holes and	stains				Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Parts missi	ing				Wipers (front & rear)	~		
Dashboa	ra	-				Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanisms Comhelt						Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	10	Kms:		Reversing camera			~
Inspected by: John Lindsay						Date: 20 Feb 2020			
I have read	and understood th	is condition o	juide. Name:			Signature:			