

## **Basic Vehicle Condition Guide**

Report ID: 19,244,974


Version: 3

Created: 12 Feb 2020

Make: Model: Hyundai lload **Body Style:** Van Year: 2014 Registration: HTT130 Reg Expiry: 24 Feb 2020 WoF Expiry: **Odometer:** 11 Feb 2021 115,942 Kms **Good No:** 19244974 VIN: KMFWBX7KLEU64259 Next Service: 128000 Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Wet

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments			
Seats	Good		
Carpets	Hole in drivers carpet		
Panels	Scratches left front panel		
Dashboard	Scratches		

## **General Comments**

Rattle from engine

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: John Lindsay Date: 13 Jan 2020

Cleate	u. 12	- 1 CD 2	.020
	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise		~	
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch	\( \times \)		
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	4.0 m		mm
Right front	5.0		mm
Left rear	4.0		mm
Right rear	4.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater		ļ	-
Operation	~		
Electrical / Accessories	l		1
Head lights	~		
Tail lights	~		
Indicators			
Dashboard warning lights	~		
Wipers (front & rear)	\( \times \)		
Window winder FL	~		
Window winder FR	~		
Window winder RL			V
Window winder RR			·
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		
Central locking	·		
Remote locking	•		
Sat. Nav. (basic test only)			./
Reversing camera	.,		
neversing Camera			

I have read and understood this condition guide.

Name: .....

Signature: .....