

Report ID: 19,245,613 Version: 2 15 May 2020 Created:

Make:	Ford	Model:	Focus	Body Style:	Wagon		Pass	Fail	N/A	
Year:	2013	Registration:	HBF265	Reg Expiry:	10 Jun 2020	Engine				
WoF Expiry:	04 Dec 2020	Odometer:	143,714 Kms	Good No:	19245613	Oil level	~			
VIN:	WF0LXXGCBLDA2759	Next Service:	163200	Service Histor	<b>y:</b> No	Smoke & fumes	~			
						Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	nical inspection prior to	purchase and t	his can be arranged fo	or an additional of	charge.	Coolant condition	~			
					Р	Performance	~			
Key:	DSC	-0	D DP			Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent R= ruct SW						Operation	~			
R = rust PT = paint defect						Noise	~			
C = crack						Clutch			~	
P = pin dent						CV joints	~			
* = decals R SC 919 D						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SC W SC D DW						Performance	~			
		Note: son		may not be disr	blaved in the diagram	Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftyre	 ><)	
Windscreen cracked in cva						Left front	Tyres (lowest observed tread depth of tyres)   Left front 5.0 mm			
						Right front			mm	
						Left rear	-	.0	mm	
								.0	mm	
Conditions During Body Inspection:						Right rear 7.0 mm				
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
Key blade loose						Suspension	L .			
Key blade i	oose					Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
		Air Conditioning / Heater								
Interior Comments						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Tear centre	e seat stained				Head lights	~			
Carpets	Good					Tail lights	~			
						Indicators	~			
Panels	Good					Dashboard warning lights	~			
Dashboa	Good					Wipers (front & rear)	~			
	iiu					Window winder FL	~			
	_					Window winder FR	~			
General Comments						Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
,						Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~	
							I	1		
Inspected by: John Lindsay Date: 09 Dec 2019										

I have read and understood this condition guide.

Name: .....

Signature: .....