

Report ID: 19,245,989 Version: 1 02 Dec 2019 Created:

Make:	Mitsubishi	Model:	Triton	Body Style:	Utility		Pass	Fail	N/A	
Year:	2012	Registration:	GKQ973	Reg Expiry:	17 Apr 2020	Engine				
WoF Expiry:	23 Sep 2020	Odometer:	176,777 Kms	Good No:	19245989	Oil level	~			
VIN:	MMAENKA40CD00707	Next Service:	187000	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~			
	S D W					Performance	~			
Key:	ISD IIW	-0	S D R	$- \square$		Radiator / Hoses (visual)	~			
S = scratch						Transmission	n			
D = dent R = rust	scw bla			715		Operation	~			
PT = paint defe		F		$\left(\left \left(\right) \right\rangle \right)$		Noise	~			
C = crack					R SC	Clutch	~			
P = pin dent	HID				74114	CV joints	~			
* = decals D R PT SC 919						Wheel bearings	~			
SC = stone chips						Brakes				
W = significant scuffs SDRW W SDRW W						Performance	~			
Podylog	action Commonts	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~			
body inspection comments						Tyres (lowest observed tread depth of tyres)			<u>)</u> 25)	
Light on flat bed rail Right side a pillar dent and paint defect						Left front 2 mm				
Right sill dent and paint defect Aerial hole on roof						Right front			mm	
Aerial hole on roof Left front tyres outer edge wear						Left rear	2 mm		mm	
Conditions During Body Inspection: Dry						Right rear	2 mm			
Conditions During Body Inspection: Dry						Spare	Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
Roof lining stains						Suspension performance	~			
Key not working Front underbody oxidisation						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			1	
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	stains, driv	stains, driver seat worn				Head lights	~			
<u></u>	left mat rir	oped, driver carp	et rin			Tail lights	~			
Carpets	letemating	opeu, unver carp	ettip			Indicators	~			
Panels	scratches					Dashboard warning lights	~			
	constation	, scratches					~			
Dashboa	rd					Wipers (front & rear) Window winder FL	~			
	1					Window winder FR	~			
General Comments						Window winder RL			~	
						Window winder RR			~	
						Rear view mirrors	~			
						Radio (basic test only)	~			
CD (basic test only)										
						Number of keys	1	✓ ✓		
Road Conditions During Test Drive: Dry Central locking										
			•			Remote locking	~	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~	
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~	
Inspected by: Kyle Mills-Brown Date: 02 Dec 2019										

I have read and understood this condition guide.

Name:

Signature: