

Report ID: 19,246,512 Version: 1 20 Nov 2019 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2012	Registration:		Reg Expiry:	15 Jan 2020	Engine	1	I	1
WoF Expiry:		Odometer:	218,365 Kms	Good No:	19246512	Oil level	~		
VIN:	MR0EZ12G104155307	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	unting is mode	for one and miles as	Danta hava nat	heen discontined or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key: SDR SDR SDR SDRW						Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust PT = paint defect C = crack						Operation	~		
						Noise	~		
						Clutch	~		
P = pin dent						CV joints	~		
* = decals DRSC 919 SD						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SD SD PT SD SD R PT						Performance	~		
Noto: como defecto & blomicheo may not be displayed in the diagram						Hand Brake	~		
Body inspection Comments						Tyres (lowest observed tread	d depth	of tyre	⊥ es)
Right side sill paint defect Light on canopy									mm
Rear bumper alignment						Right front		- 	mm
Centre brake light cracked Aerial hole on roof						Left rear		3	mm
Conditions During Body Inspection: Dry						 Right rear		 9	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Key doesn't work on door Slight underbody oxidisation						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats Average						Head lights	~		
	driver mat	hole				Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	. left front c	upholder cover i	missing			Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking		~	
,						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Yes Kms: 144,000						Reversing camera			~
Inspected by: John Lindsay Date: 20 Nov 2019									
Inspected by. John Linusay Date: 20 NOV 2019									

I have read and understood this condition guide.

Name:

Signature: