

Report ID: 19,247,125 Version: 1 13 Nov 2019 Created:

Make:	lsuzu	Model:	D-MAX	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:	JLH743	Reg Expiry:	29 Jan 2020	Engine			
WoF Expiry:	30 Oct 2019	Odometer:	132,460 Kms	Good No:	19247125	Oil level	~		
VIN:	MPATFR85JFT003543	Next Service:	130000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		f	. Danta harra mat	haan diamanda daa	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged f	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SD SDR		S D	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
R = rust				Γ	THIA	Noise	~		
PT = paint def C = crack				+	SC	Clutch	~		
P = pin dent	Ho					CV joints	~		
* = decals RSC PIP						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D S D R W W S D						Performance			
		Notorcom					~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<u>.</u>	
Left rear mudflap missing						Tyres (lowest observed tread depth of tyres)			
						Left front	5		mm
						Right front	6		mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5 n		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Gearbox oil	leak					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonte						Operation 🖌			
Interior Comments stains, driver seat hole						Electrical / Accessories			
Seats	stains, driv	ver seat hole				Head lights	~		
Carpote	front mats	worn, driver car	pet worn			Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dealahaa	shifter not	oworn				Wipers (front & rear)	~		
Dashboa	iiu					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking			~
Remote lo						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test of									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Kyle Mills-Brown Date: 13 Nov 2019									

I have read and understood this condition guide.

Name:

Signature: