

Report ID: 19,252,584 Version: 1 29 Oct 2019 Created:

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2013	<b>Registration:</b>	GYD519	Reg Expiry:	18 Mar 2020	Engine			
WoF Expiry:	14 Jun 2020	Odometer:	193,603 Kms	Good No:	19252584	Oil level	~		
VIN:	MNAUM1F50DW1769	Next Service:	195748	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	is can be arranged to	i an additional C	narge.	Coolant condition	~		
	D PT SC W		S D PT W S R			Performance	~		
Key: S = scratch						Radiator / Hoses (visual)	~		
						Transmission			
R = rust SPT SC W A A						Operation	~		
PT = paint defect						Noise	~		
C = crack					RSC	Clutch	~		
P = pin dent						CV joints	~		
						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	P SC	C	S D			Performance	~		
Body Inst	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Spare wheel needs to be replaced						Tyres (lowest observed tread depth of tyres)			es)
					Left front	7		mm	
						Right front	7	7	mm
						Left rear	5	5	mm
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Engine guard dented Slight oxidation						Suspension performance	~		
No significant underbody damage						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Drivers sea	at worn and stain	is on seats			Head lights	~		
Carpote	Average					Tail lights	<		
Carpets						Indicators	۲		
Panels	Scratches	on panels				Dashboard warning lights	<		
Dashboa	rd Screw hole	es in centre cons	ole,scratches			Wipers (front & rear)	~		
						Window winder FL	~		
	·					Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Timing Mechanism: Timing Chain						Remote locking	~		
_						Sat. Nav. (basic test only)			~
Evidence	or Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Kyle Mills-Brown Date: 29 Oct 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....