

Report ID: 19,253,037 Version: 2 15 Nov 2019 Created:

Make:	Toyota	Model:	Corolla	Body Style:	Sedan			Pass	Fail	N/A
Year:	2015	Registration:	JET653 Reg Expiry: 29 Dec 2019			Engine				
WoF Expiry:	25 Jun 2020	Odometer:	147,227 Kms	Good No: 19253037		Oil level		~		
VIN:	MR053REH205274938	Next Service:	150000	Service Histor	y: Yes	Smoke &	& fumes	~		
						Perform	ance	~		
	port is not a warranty	pration is made	for age and mileage	Parts have not	been dismantled or	Noise		~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full machanisal inspection prior to purchase and this can be arranged for an additional charge.						Cooling S	ystem			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant	condition	~		
	SC W		S D P		S	Perform	ance	~		
Key:		-0				Radiator	r / Hoses (visual)	~		
S = scratch D = dent						Transmis	Transmission			
D = dent R = rust	SC W			715	S D PT W	Operatio	on	~		
PT = paint defe	ect NP			$\left(\left \left(\right) \right\rangle \right)$		Noise		~		
C = crack					S SC	Clutch				~
P = pin dent	s sc dR				74 <u>11</u> 4	CV joint	S	~		
* = decals				10	ED PT W	Wheel b	earings	~		
SC = stone chips W = significant scuffs						Brakes				
W = significant scurs PSC W D D W P						Performance		~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Br	ake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)				es)
						Left front 6			mm	
						Right front		6	6 mm	
						Left rear		4	ļ	mm
Conditions During Body Inspection: Wet						Right rear		5 mm		
						Spare			Yes	
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspens	ion performance	~		
						Steering	performance	~		
						Shock al	bsorbers	~		
						Air Conditioning / Heater				
						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Stains on s	eats				Head lig	hts	~		
Comoto	Good					Tail light	ts	~		
Carpets						Indicato	rs	~		
Panels	Good					Dashboa	ard warning lights	~		
	Good	Good				Wipers (front & rear)	~		
Dashboa	iiu					Window	winder FL	~		
	_					Window	v winder FR	~		
General C	<u>Comments</u>					Window	winder RL	~		
						Window	v winder RR	~		
						Rear vie	w mirrors	~		
						Radio (b	asic test only)	~		
						CD (basi	c test only)	~		
						Number of keys 2				
Road Conditions During Test Drive: Wet						Central	locking	~		
						Remote	locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav	. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversir	ig camera	~		
Inspected by: Neil Honeyman Date: 15 Nov 2019										
Inspected by: Neil Honeyman Date: 15 Nov 2019										

I have read and understood this condition guide.

Name:

Signature: