

Basic Vehicle Condition Guide

Report ID: 19,253,282


Version: 3

Created: 22 Oct 2019

Make: Model: Holden Cruze **Body Style:** Sedan Year: 2016 Registration: **KBN278** Reg Expiry: 19 Dec 2019 WoF Expiry: **Odometer: Good No:** 22 Oct 2020 155,944 Kms 19253282 VIN: 6G1PE5EN9GL246468 Next Service: 60000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | | |
|--------------------------|---------|--|--|--|
| Seats | Average | | | |
| Carpets | Average | | | |
| Panels | Average | | | |
| Dashboard | Average | | | |

| | _ |
|---------|----------|
| General | Comments |

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Kyle Mills-Brown

Kms:

| | Pass | Fail | N/A | | | |
|--|------------------|---------|-----|--|--|--|
| Engine . | | | • | | | |
| Oil level | ~ | | | | | |
| Smoke & fumes | \ \ \ | | | | | |
| Performance | ~ | | | | | |
| Noise | ~ | | | | | |
| Cooling System | | | | | | |
| Coolant condition | > | | | | | |
| Performance | V | | | | | |
| Radiator / Hoses (visual) | ~ | | | | | |
| Transmission | | | | | | |
| Operation | ~ | | | | | |
| Noise | ~ | | | | | |
| Clutch | | | ~ | | | |
| CV joints | > > | | | | | |
| Wheel bearings | ~ | | | | | |
| Brakes | | | | | | |
| Performance | ' | | | | | |
| Hand Brake | ~ | | | | | |
| Tyres (lowest observed tread | l depth | of tyre | es) | | | |
| Left front | 4.0 | | mm | | | |
| Right front | 4.0 | | mm | | | |
| Left rear | 8.0 | | mm | | | |
| Right rear | 8.0 | | mm | | | |
| Spare | | Yes | | | | |
| Suspension | | | | | | |
| Suspension performance | ~ | | | | | |
| Steering performance | V | | | | | |
| Shock absorbers | / | | | | | |
| Air Conditioning / Heater | | | | | | |
| Operation | | | | | | |
| Electrical / Accessories | | | | | | |
| Head lights | • | | | | | |
| Tail lights | V | | | | | |
| Indicators | V | | | | | |
| Dashboard warning lights | > > | | | | | |
| Wipers (front & rear) Window winder FL | ~ | | | | | |
| Window winder FR | ~ | | | | | |
| Window winder RL | | | | | | |
| Window winder RR | / | | | | | |
| Rear view mirrors | <i>v</i> | | | | | |
| Radio (basic test only) | <i>v</i> | | | | | |
| CD (basic test only) | <i>v</i> | | | | | |
| Number of keys | 2 | | | | | |
| Central locking | · | | | | | |
| Remote locking | V | | | | | |
| | • | | | | | |
| Sat. Nav. (basic test only) | ~ | | | | | |

I have read and understood this condition guide.

Name:

Signature:

10 Oct 2019

Date: