

Report ID: 19,253,572 Version: 1 02 Oct 2019 Created:

Make:	Holden	Model:	Colorado	Body Style:	Utility		Pass	Fail	N/A
Year:	2009	Registration:	EWH354	Reg Expiry:	10 Feb 2020	Engine			
WoF Expiry:		Odometer:	98,143 Kms	Good No:	19253572	Oil level	~		
VIN:	MMMTFS85H9H5177(			Service Histor		Smoke & fumes	~		
			100000		• 163	Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.									
				_		Performance	~		
Key:	S W	-0	D SR		S	Radiator / Hoses (visual)	~		
S = scratch						Transmission	<ul> <li>✓</li> </ul>		
D = dent									
R = rust				10	SAILY	Operation	~		
PT = paint defe	ect H					Noise	~		
C = crack P = pin dent						Clutch	~		
* = decals SSC PIP						CV joints	~		
SC = stone chips						Wheel bearings	✓		
W = significant scuffs						Brakes			
		N			level in the diamene	Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~	<u> </u>	Ļ
Aerial holes on roof						Tyres (lowest observed tread depth of tyres)			
Light mounting points on roof						Left front	8 mm		
						Right front	-	9	mm
						Left rear			mm
Conditions During Body Inspection: Wet						Right rear	10 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
onder Carnage & onder bonnet inspection comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments Hole in drivers seat						Electrical / Accessories		1	
Seats		vers seal				Head lights	~		
Carpets	Hole in dri	vers carpet				Tail lights	~		
	C and take a					Indicators	~		
Panels	Scratches	on rear panels				Dashboard warning lights	~		
Dashboa	rd Screw hole	es in centre cons	ole			Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Wet						Central locking	~		
Engine Timing Mechanisms Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Kyle Mills-Brown Date: 02 Oct 2019									

Name: .....