

Basic Vehicle Condition Guide

Report ID: 19,253,586


Version: 2

Created: 14 Oct 2019

Make: Model: Subaru Outback **Body Style:** SUV Year: 2015 Registration: JLB243 Reg Expiry: 25 Nov 2019 WoF Expiry: **Odometer:** 11 Oct 2020 115,128 Kms **Good No:** 19253586 VIN: JF2BS9KC2FG014818 Next Service: 126500 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Engine oil leak

| Interior Comment | <u>S</u> |
|------------------|------------------------|
| Seats | Stains on rear seat |
| Carpets | Hole in drivers carpet |
| Panels | Average |
| Dashboard | Average |

General Comments

_

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: John Lindsay Date: 03 Oct 2019

Name:

| 4. | | V ss) |
|---------------------------------------|-----|----------|
| y y y y y y y y y y y y y y y y y y y | .0 | |
| y y y y y y y y y y y y y y y y y y y | .0 | |
| y y y y y y y y y y y y y y y y y y y | .0 | |
| y y y y y y y y y y y y y y y y y y y | .0 | |
| y y y y y y y y y y y y y y y y y y y | .0 | |
| epth 4. | .0 | |
| 4. | .0 | |
| 4. | .0 | |
| 4. | .0 | |
| 4. | .0 | |
| 4. | .0 | |
| 4. | | 1111111 |
| | () | |
| 7.0 | | mm |
| | | mm |
| 7. | | mm |
| | Yes | |
| . | | |
| / | | |
| / | | |
| / | | |
| | | |
| / | | |
| | | |
| / | | |
| / | | |
| / | | |
| / | | |
| / | | |
| / | | |
| / | | |
| / | | |
| / | | |
| / | | |
| | | |
| / | | |
| <u> </u> | | |
| | | V |
| / | | |
| | | ./ |
| , | | • |
| | | |
| | | |

Signature: