

Report ID: 19,253,921


Version: 1

Created: 08 Oct 2019

Make:	Isuzu	Model:	D-MAX	Body Style:	Utility
Year:	2018	Registration:	LJA605	Reg Expiry:	23 Apr 2020
WoF Expiry:	24 Apr 2021	Odometer:	31,177 Kms	Good No:	19253921
VIN:	MPATFR85JJT001069	Next Service:	45000	Service Histor	y: No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Bad repair to right rear door Left front tyre outer edge wear

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Interior Comments					
Seats	Average				
Carpets	Good				
Panels	Both rear panels scratched				
Dashboard	Scratches				

## **General Comments**

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	> >		
Performance	>		
Noise	~		
Cooling System		•	•
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	<i>v</i>		
Transmission			
Operation	<b>'</b>		
Noise	>		
Clutch	\( \times \)		
CV joints	<b>'</b>		
Wheel bearings	>		
Brakes			
Performance	>		
Hand Brake	>		
Tyres (lowest observed tread	l depth	of tyre	es)
Left front	***	3	mm
Right front	4	4	mm
Left rear	4	4	mm
Right rear	4	4	mm
Spare		Yes	
Suspension			
Suspension performance	<b>'</b>		
Steering performance	>		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	/		
Tail lights	~		
Indicators	<ul><li>V</li><li>V</li><li>V</li><li>V</li><li>V</li><li>V</li></ul>		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	~		
Rear view mirrors	<b>'</b>		
			I
Radio (basic test only)	<b>'</b>		
Radio (basic test only)  CD (basic test only)			
CD (basic test only)  Number of keys	✓ ✓ 2		
CD (basic test only)	<b>V</b>		
CD (basic test only)  Number of keys	✓ ✓ 2		

Reversing camera

Name: .....

08 Oct 2019

Signature: .....

John Lindsay