

Basic Vehicle Condition Guide

Report ID: 19,254,695


Version: 1

Created: 18 Sep 2019

Make: Model: Toyota Hiace **Body Style:** Van Year: 2013 Registration: GZW800 Reg Expiry: 07 Nov 2019 **Odometer:** WoF Expiry: 05 Sep 2020 28,486 Kms **Good No:** 19254695 VIN: JTFPT22P400011554 **Next Service:** 42000 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Left side sill damaged Paint defect in drivers door opening

Conditions During Body Inspection:

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt **Evidence of Cam Belt Replacement:**

No

Kms:

Inspected by: John Lindsay

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance			
Radiator / Hoses (visual)	ν ν		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		ļ •
Wheel bearings	•		
Brakes			
Performance	~		
Hand Brake	./		
Tyres (lowest observed tread	l denth	of tyre)
Left front			
Right front		7	mm
Left rear	8		mm
-	7		mm
Right rear	7		mm
Spare		Yes	
Suspension			
Suspension performance	•		
Steering performance	V		
Shock absorbers	•		
Air Conditioning / Heater			
Operation	/		
Electrical / Accessories		I	
Head lights	~		
Tail lights	~		
Indicators	\(\times \) \(\t		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	3		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		
Date: 18 Sen 201			

Signature: