

Report ID: 19,256,361 Version: 1 07 Aug 2019 Created:

Make:	Hyundai	Model:	lload	Body Style:	Van		Pass	Fail	N/A
Year:	2013	Registration:		Reg Expiry:	18 Oct 2019	Engine		-	
WoF Expiry:		Odometer:	109,506 Kms	Good No:	19256361	Oil level	~		
VIN:	KMFWBX7KLDU57357	Next Service:		Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	S D PT	-0	S D R PT S			Radiator / Hoses (visual)	~		
S = scratch	Se	20			X	Transmission	V		
D = dent	SDCSCW				BIDSDW				<u> </u>
R = rust				10		Operation	~		
PT = paint defe	ect			+	R SC	Noise	~		
C = crack P = pin dent	LH					Clutch	~		<u> </u>
* = decals	R SC DC				ELA SD	CV joints	~		<u> </u>
SC = stone chips						Wheel bearings	~		
W = significant scuffs S D S D S D S D						Brakes			
						Performance	~		<u> </u>
Body Insp	pection Comments	Note: som	ne defects & blemishe	es may not be disp	layed in the diagram	Hand Brake	~		
Windscreen stone chip						Tyres (lowest observed tread depth of tyres)			
						Left front	8	6	mm
						Right front	8	6	mm
						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	4	ŀ	mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Only one re	emote working					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Drivers sea	at worn and stain	is on seats			Head lights	~		
	Hole in dri	ivers mat and car	pet worn			Tail lights	~		
Carpets			-			Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Scratches					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
	· ·					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		L
Boad Con	ditions During Tes	t Drive:				Central locking	~		
			Dry			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
L									
Inspected	d by: John Lindsay					Date: 07 Aug 20	19		

Name:

Signature: