

Basic Vehicle Condition Guide

Report ID: 19,256,498


Version: 1

Created: 05 Aug 2019

Make: Model: Nissan Navara **Body Style:** Utility Year: 2018 Registration: LMP6 Reg Expiry: 18 Oct 2019 **Odometer:** WoF Expiry: **Good No:** 19 Jul 2021 24,945 Kms 19256498 VIN: MNTCB2D23A001226: Next Service: 38000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Chip windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| <u>Interior Comments</u> | | | |
|--------------------------|--------------------------|--|--|
| Seats | stains, driver seat worn | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

05 Aug 2019 Inspected by: John Lindsay Date:

Name:

| | Pass | Fail | N/A | |
|--|--------------|------|-----|--|
| Engine | | | | |
| Oil level | ~ | | | |
| Smoke & fumes | ~ | | | |
| Performance | \(\times \) | | | |
| Noise | ~ | | | |
| Cooling System | l | 1 | | |
| Coolant condition | ~ | | | |
| Performance | <i>v</i> | | | |
| Radiator / Hoses (visual) | ~ | | | |
| Transmission | | | | |
| Operation | ~ | | | |
| Noise | ~ | | | |
| Clutch | \(\times \) | | | |
| CV joints | ~ | | | |
| Wheel bearings | ~ | | | |
| Brakes | | • | | |
| Performance | ~ | | | |
| Hand Brake | ~ | | | |
| Tyres (lowest observed tread depth of tyres) | | | | |
| Left front | | 4 | mm | |
| Right front | | 6 | mm | |
| Left rear | | 4 | mm | |
| Right rear | 4 | | mm | |
| Spare | | Yes | | |
| Suspension | | | | |
| Suspension performance | ~ | | | |
| Steering performance | ~ | | | |
| Shock absorbers | ~ | | | |
| Air Conditioning / Heater | | | | |
| Operation | ~ | | | |
| Electrical / Accessories | | | | |
| Head lights | ~ | | | |
| Tail lights | ~ | | | |
| Indicators | v | | | |
| Dashboard warning lights | ~ | | | |
| Wipers (front & rear) | ~ | | | |
| Window winder FL | ~ | | | |
| Window winder FR | ~ | | | |
| Window winder RL | ~ | | | |
| Window winder RR | ~ | | | |
| Rear view mirrors | • | | | |
| Radio (basic test only) | V | | | |
| CD (basic test only) | ~ | | | |
| Number of keys | 2 | | | |
| Central locking | • | | | |
| Remote locking | ~ | | | |
| Sat. Nav. (basic test only) | | | ~ | |
| Reversing camera | | | | |

Signature: