

Report ID: 19,256,553 Version: 1 Created: 01 Aug 2019

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2009	Registration:	EZG672	Reg Expiry:	07 Jun 2020	Engine	1 035	1 011	
WoF Expiry:	2009 29 Apr 2020	Odometer:	284,570 Kms	Good No:	07 Jun 2020 19256553	Oil level	~		
VIN:	MNALS2E908W74761			Service Histor		Smoke & fumes	~		<u> </u>
	WINAL322908W74701	Next Service.	290000	Service mistor	• 110	Performance	~		<u> </u>
	port is not a warranty					Noise	~		
	a guide only. Conside sting undertaken. The					Cooling System	V		
	ical inspection prior to					Coolant condition			<u> </u>
						Performance	<b>v</b>		
Key:	S	-0	SDRPTW SDR		S D R PT W	Radiator / Hoses (visual)	ン ン		
S = scratch	Se	20		1000	X	Transmission	V		
D = dent	S D PT SCI			1 - L	BIDSDPTW				1
R = rust				10		Operation Noise	マ マ		
PT = paint def C = crack	ect M			+	R PT SC	Clutch	-		
P = pin dent	Ho	KI					<b>v</b>		
* = decals	DRPTSC DR				SRPT SC V	CV joints	~		
SC = stone chips						Wheel bearings	~		
W = significant scuffs SP SDRPTW SDRPT SDRPTW						Brakes			T
		Nata				Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	•	<u>.</u>	Ļ
Slight under bonnet oxidisation						Tyres (lowest observed tread			
Front bumper alignment Right sill paint defect						Left front	ç		mm
Left sill pair	it defect and dents					Right front	ç		mm
Canopy locks broken						Left rear	5		mm
Conditions During Body Inspection: Dry						Right rear	5 mn		mm
Under Carriage & Under Bennet Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments AC not getting cold					Suspension			1	
Light on ca	5					Suspension performance	~		
	nder flare alignment					Steering performance	~		
	iator support strut leaking					Shock absorbers	~		
5	5					Air Conditioning / Heater			<del></del>
Interior Comments						Operation		~	
Holes in drivers seat, stains on seats						Electrical / Accessories			T
Seats			onseuts			Head lights	~		
Carpets	Average					Tail lights	~		
	A					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd gauge sur	round loose				Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Canada						Window winder FR	~		<u> </u>
General Comments Engine/gearbox oil leak						Window winder RL			~
Minor unde	rbody oxidisation					Window winder RR			~
	e housing leaking					Rear view mirrors	~		
Fuel tank p	DSSIDIE IEAK					Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		
<b>F</b> ue <b>t</b> = - <b>T</b> •						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Increate	d by John Linder					Data: 01 Aug 20	10		
Inspecte	d by: John Lindsay					Date: 01 Aug 20	לו		
I have read	and understood th	is condition q	juide. Name: .			Signature:			