

Basic Vehicle Condition Guide

Report ID: 19,256,728


Version: 1

Created: 31 Jul 2019

Make: Model: APV Suzuki **Body Style:** Van Year: 2008 Registration: ENP471 Reg Expiry: 29 Jun 2020 **Odometer:** WoF Expiry: 06 Dec 2019 186,217 Kms **Good No:** 19256728 VIN: MHYGDN71V0030035 **Next Service:** 190000 **Service History:**

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Remote not working

Underbody oxidisation radiator support

<u>Interior Comments</u>			
Seats	driver seat rips		
Carpets	driver carpet holes		
Panels	Average		
Dashboard	Average		

General Comments

Release bearing worn

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

John Lindsay

Evidence of Cam Belt Replacement: No Kms:

Date: 31 Jul 2019

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	\(\times \)			
Performance	~			
Noise	~			
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	~			
Transmission	•			
Operation	~			
Noise	~			
Clutch		~		
CV joints	~			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread	depth	of tyre	es)	
Left front	5		mm	
Right front	6		mm	
Left rear	7		mm	
Right rear	4		mm	
Spare	Yes			
Suspension				
Suspension performance	~			
Steering performance	<i>V</i>			
Shock absorbers	~			
Air Conditioning / Heater	ı		ı	
Operation 🗸				
Electrical / Accessories	I			
Head lights	~			
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	\(\times \)			
Window winder FL	~			
Window winder FR	~			
Window winder RL			~	
Window winder RR			~	
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1	l	-	
Central locking	~			
Remote locking		~		
Sat. Nav. (basic test only)		-	~	
Reversing camera			~	

I have read and understood this condition guide.

Name:

Signature: