

Report ID: 19,257,117 Version: 1 25 Jul 2019 Created:

Make:	Mercedes-Benz	Model:	C63	Body Style:	Sedan		Pass	Fail	N/A
Year:	2008	Registration:	LNA662	Reg Expiry:	17 Jul 2019	Engine			
WoF Expiry:	18 Jul 2019	Odometer:	124,966 Kms	Good No:	19257117	Oil level	~		
VIN:	WDD2040772F184632	Next Service:	127464	Service Histor	y: No	Smoke & fumes	~		
No. The						Performance	~		
	port is not a warranty a guide only. Conside		for age and mileage	. Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a fuil mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition	~		
	PT C W				R	Performance	~		
Key: S = scratch						Radiator / Hoses (visual)	~		
						Transmission			
R = rust SCW SPT						Operation		~	
PT = paint defect						Noise	~		
C = crack						Clutch			~
P=pin dent						CV joints	~		
* = decals SC = stone chips						Wheel bearings	~		
W = significant scuffs						Brakes			
S P S PT W						Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake	~		
All four tyres inner edge wear						Tyres (lowest observed tread depth of tyres)			
					Left front	4 mm			
					Right front	5 mm		mm	
						Left rear	2 mm		
Conditions During Body Inspection: Dry						Right rear	2 mm		
						Spare No			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
ASB and ESP faulty Run flat faulty						Suspension performance	~		
Cruise control and speedtronic faulty						Steering performance		~	
AC not getting cold Differential oil leak						Shock absorbers	~		
	ning light stays on					Air Conditioning / Heater	1		
Interior Comments						Operation		~	
Both front seats worp, marks on rear seat						Electrical / Accessories			
Seats	bournoin		is officer scat			Head lights	~		
Carpets	Average					Tail lights	~		
	Scratch or	n right rear panel				Indicators	~		
Panels		ingini icai panel				Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Ganaral	omments					Window winder FR	~		
General Comments Handbrake warning light stays on						Window winder RL	~		
Power steering heavy and noisy						Window winder RR	~		
Harsh engagement into reverse Hesitation in changing up through the gears						Rear view mirrors	~		
		gears				Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking			~
Engine Timing Mechanism: Timing Chain						Remote locking	~		
						Sat. Nav. (basic test only)			~
Evidence	ог сапт вен керіас	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 25 Jul 2019									

I have read and understood this condition guide.

Name:

Signature: