

Report ID: 19,269,758 Version: 2 17 Dec 2019 Created:

Make:	Nissan	Model:	Sunny	Body Style:	Sedan		Pass	Fail	N/A
Year:	2004	Registration:	HEH990	Reg Expiry:	31 Oct 2019	Engine	1		
WoF Expiry:	17 Apr 2020	Odometer:	171,447 Kms	Good No:	19269758	Oil level	~		
VIN:	7AT0DH14X11395448	Next Service:	0	Service Histor	V: No	Smoke & fumes	~		
						Performance	V		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S SC S	-0	S D SC S SC		S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	SDCSC			The	SDC	Operation	~		
R = rust PT = paint defe				\prod	THA	Noise	~		
C = crack				$+ \mathbf{\nabla}$	S SC	Clutch			~
P = pin dent					세비	CV joints	~		•
* = decals	SDSC 916			The	ELL SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S D SC S S S D SC S S S D SC						Performance	~		
		Note: son	ne defects & blemishes	mav not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							Tyres (lowest observed tread depth of tyres)		
Minor stone chips in the windscreen ,RF indicator lens broken,headlights need attention frosty ,						Left front 6 mm			
						Right front	7		mm
						Left rear			mm
Can ditiona Dunia a Dadu la su artica.						Right rear	4 mm 4 mm		
Conditions During Body Inspection: Dry						Spare	4 mm Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Oil leaks,needs a service ,						Suspension performance	~		
	,					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation		~	
Interior Comments						Electrical / Accessories		•	
Seats	cigarette h	oles in seats,wea	ar and tear,stained ,			Head lights	~		
						Tail lights	~		
Carpets	wear and t	ear,minor stains	,			Indicators	~		
Panels	door trims	ripped,middle c	onsole lid broken ,			Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	2 V		
Koad Con	aitions During Test	Drive:	Dry			Remote locking			~
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence of Cam Belt Replacement: Not Applicable Kms: Reversing camera								~	
Inspected by: Donovan Matara Date: 17 Dec 2019									

I have read and understood this condition guide.

Name:

Signature: