

Report ID: 19,272,314 Version: 1 Created: 10 Mar 2020

Make:	Ford	Model:	Ranger	Body Style:	Utility		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	-	Reg Expiry:	30 Jul 2020	Engine	1		1
WoF Expiry:	12 Mar 2021	Odometer:	403,010 Kms	Good No:	19272314	Oil level	~		1
VIN:	MNAUSFE90AW90439	Next Service:	412000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		1
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		1
						Performance	~		<u> </u>
Key:	S*	-0	S* S*	-01-	S*	Radiator / Hoses (visual)	~		+
S = scratch	RE	A U			Ton l	Transmission	-		1
D = dent	S* 6/6				S*	Operation	~		1
R = rust PT = paint def				$\prod$		Noise	~		
C = crack				+		Clutch	V		
P = pin dent					ᅰЦ	CV joints	~		+
* = decals	SD* 916		<u> </u>	- AL	ETP S*	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S* S* S* S*						Performance			
Note: come defecte % blomiches may not be dienlayed in the diagram						Hand Brake	~		
Body inspection comments									
Oil leaks						Tyres (lowest observed tread depth of tyres)   Left front 8.0 mm			
						Right front			mm
						Left rear	8		mm mm
			_					.0	-
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Play front hubs						Suspension			1
Flay HOILE H	ubs					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	nveluge					Head lights	~		
Carpets	Average					Tail lights	~		<u> </u>
	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
						Window winder FR	~		
General Comments Rust under body						Window winder RL	~		
Rust under	body					Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	10	Kms:		Reversing camera			~
Increasted byloff Luke						Data: 10 Mar 2020			
Inspected by: Jeff Luke Date: 10 Mar 2020									
I have read	and understood th	is condition c	uide. Name:			Signature:			