

Basic Vehicle Condition Guide

Report ID: 19,273,051


Version:

Created: 30 Apr 2020

Make: Model: Hyundai lload **Body Style:** Van Year: 2013 Registration: HDH424 Reg Expiry: 31 Jul 2020 WoF Expiry: **Odometer:** 22 Nov 2020 154,074 Kms **Good No:** 19273051 VIN: KMFWBX7KLEU59068. **Next Service:** Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Oil low

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Service Due next 158,000kms

Interior Comm	<u>ents</u>
Seats	Poor
Carpets	Poor
Panels	Average
Dashboard	Average

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

13 Feb 2020 Inspected by: Jeff Luke

	Pass	Fail	N/A
Engine			
Oil level		~	
Smoke & fumes	~		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	\(\triangle \)		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	3	.0	mm
Right front	3	.0	mm
Left rear	2	.0	mm
Right rear	2.0		mm
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	V		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	\(\times \)		
Window winder FL	~		
Window winder FR	~		
Window winder RL			~
Window winder RR			~
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	1		
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera			~

I have read and understood this condition guide.

Name:

Signature: