

Report ID: 19,275,625 Version: 1 11 Nov 2019 Created:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2012	Registration:	GMF121	Reg Expiry:	20 Aug 2020	Engine			
WoF Expiry:	17 Aug 2020	Odometer:	161,957 Kms	Good No:	19275625	Oil level	~		
VIN:	MR0EZ12G804012340	Next Service:	166900	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	lical inspection prior to	purchase and ti	his can be arranged to	r an additional c	narge.	Coolant condition	~		
			S S			Performance	~		
Key:		=		5(0)-		Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
R = rust	s AR			10	HI IS	Operation	~		
PT = paint def	ect NP					Noise	~		
C = crack				TTY,		Clutch	~		
P = pin dent	HIP				74HL	CV joints	~		
* = decals		10		10		Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
	S D		S S			Performance	~		
Body Inst	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	4	.0	mm
						Right front	4	.0	mm
						Left rear	2	.0	mm
Conditions During Body Inspection: Dry						Right rear	2.0 mm		mm
						Spare Yes			
Under Ca	rriage & Under Bor	inet Inspectio	on Comments			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Commonts						Operation 🖌			
Interior Comments Good						Electrical / Accessories			
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		<u> </u>
Panels	Good					Dashboard warning lights	~		<u> </u>
Dashboa	rd Good					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		
General	omments					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	v		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Engine Ti	ming Mechanism:	Cambel				Remote locking	~		
Evidence of Cam Belt Replacement: No Kms:						Sat. Nav. (basic test only)			~
						Reversing camera			~
Inspected by: Dion Mair Date: 11 Nov 2019									
<u> </u>									

I have read and understood this condition guide.

Name:

Signature: