

Report ID: 19,276,629 Version: 1 01 Oct 2019 Created:

Make:	Mazda	Model:	Mazda2	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	ELH395	Reg Expiry:	10 Jul 2020	Engine			L
WoF Expiry:	12 Mar 2020	Odometer:	167,291 Kms	Good No:	19276629	Oil level	~		
VIN:	JM0DE10Y180114244	Next Service:	176000	Service Histor	y: Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	oration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S	-0	* <u>S*</u>	-01-	S*	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s dla			715	HIL S*	Operation	~		
R = rust PT = paint defe				$\left(\left \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				74114	CV joints	~		
* = decals	s 616			-NG	FID S*	Wheel bearings		~	
SC = stone chips						Brakes			L
W = significan	t scuffs S		S* S*		S*	Performance	~		
Bodylac	action Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments						Tyres (lowest observed tread depth of tyres)			<u>)</u> 25)
								mm	
						Right front			mm
						Left rear			mm
Conditions During Body Inspection: Wet						Right rear			mm
						Spare			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Remote loc	king not working					Suspension performance	~		
						Steering performance	~		
Shock absorbers							V		
Air Conditioning / Hea							1		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	~		
Carpets	, it cluge					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	, Average					Wipers (front & rear)	~		
Dashboa	rd ///elage					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Tyres/wheel bearings noisy Vibration in drive train						Window winder RR	~		
Vibration						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Wet Central locking									
						Remote locking		~	
-	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Jeff Luke Date: 01 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: