

Report ID: 19,277,607 Version: 1 30 Oct 2019 Created:

Make:	Mazda	Model:	Mazda3	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2011	Registration:	MEH440	Reg Expiry:	26 Jan 2020	Engine			
WoF Expiry:	19 Jun 2020	Odometer:	161,609 Kms	Good No:	19277607	Oil level	~		
VIN:	JM0BL107200309592	Next Service:	0	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:	S SC	-0	S P SC S P SC		S SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust SC SSC SSC						Operation	~		
R = rust PT = paint def	ect NIP			$\left(\left \right\rangle \right)$		Noise	~		
C = crack				+	SC	Clutch			~
P = pin dent	HIG				세비	CV joints	~		
* = decals	- Ole			- No	ELD'S	Wheel bearings	~		
SC = stone chips						Brakes	•		
W = significant scuffs SC S SC S SC S SC						Performance	~		
		Note: son	he defects & blemishe	s may not be disr	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							•	oftyre	
Minor stone chips in the windscreen ,						Tyres (lowest observed tread depth of tyres) Left front 2 mm			
									mm
						Right front Left rear		3	mm
							:	3	mm
Conditions During Body Inspection: Dry						Right rear mm			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
	inage a onder bor	meemspeede	<u>Comments</u>			Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
						Electrical / Accessories			
Seats	Average					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	Average					Wipers (front & rear)	~		
						Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
, ,						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: Not Applicable Kms:						Reversing camera			~
									·
Inspected by: Donovan Matara Date: 30 Oct 2019									

I have read and understood this condition guide.

Name:

Signature: