

Basic Vehicle Condition Guide

Report ID: 19,278,491


Version: 1

Created: 15 Nov 2019

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2008 Registration: MLP344 Reg Expiry: 04 Aug 2020 WoF Expiry: **Odometer: Good No:** 01 Nov 2020 220,679 Kms 19278491 VIN: KMHSH81WR8U25505 **Next Service:** 230700 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Minor stone chips in the windscreen,

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

| Interior Comments | | | |
|-------------------|---------|--|--|
| Seats | Average | | |
| Carpets | Average | | |
| Panels | Average | | |
| Dashboard | Average | | |

Name:

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Inspected by: Donovan Matara

| Creater | u. 1. | J 140 V 2 | 2017 |
|---|--|-----------|------|
| | Pass | Fail | N/A |
| Engine | | | |
| Oil level | ~ | | |
| Smoke & fumes | ✓ ✓ | | |
| Performance | ~ | | |
| Noise | ~ | | |
| Cooling System | | | |
| Coolant condition | ~ | | |
| Performance | <i>y y</i> | | |
| Radiator / Hoses (visual) | ~ | | |
| Transmission | | | 1 |
| Operation | ~ | | |
| Noise | ~ | | |
| Clutch | | | ~ |
| CV joints | ~ | | |
| Wheel bearings | • | | |
| Brakes | | | |
| Performance | ., | | I |
| Hand Brake | • | | |
| | | - 6 + | > |
| Tyres (lowest observed tread | | | |
| Left front | 7 | | mm |
| Right front | 7 | | mm |
| Left rear | 3 | | mm |
| Right rear | : | 3 | mm |
| Spare | | Yes | |
| Suspension | | ı | |
| Suspension performance | ~ | | |
| Steering performance | ~ | | |
| Shock absorbers | ~ | | |
| Air Conditioning / Heater | | | |
| Operation | | ~ | |
| Electrical / Accessories | | | |
| Head lights | ~ | | |
| Tail lights | ~ | | |
| Indicators | ~ | | |
| Dashboard warning lights | ~ | | |
| Wipers (front & rear) | \(\times \) \(\t | | |
| Window winder FL | ~ | | |
| Window winder FR | ~ | | |
| Window winder RL | | | |
| Window winder RR | \(\times \) | | |
| Rear view mirrors | ~ | | |
| Radio (basic test only) | ~ | | |
| CD (basic test only) | ~ | | |
| Number of keys | 1 | | |
| Central locking | ~ | | |
| Remote locking | ~ | | |
| | _ | | V |
| Sat. Nav. (basic test only) | | | |
| Sat. Nav. (basic test only) Reversing camera | | | ~ |

15 Nov 2019

Signature:

Date: